4-<u>060737</u>

90846

TO: STATE CORPORATION COMMISSION	API Number: <u>15-1</u>	
STATE CORPORATION COMMISSION		63 -21,463-A .
CONSERVATION DIVISION - PLUGGING	SE NW NE /4 SEC.	<u> </u>
130 SOUTH MARKET, SUITE 2078	. <u>4290 4190 </u>	rom S section line
WICHITA, KANSAS 67202	1650 560 feet f	rom E section line
	27	
	⊬ CC	
Operator license#5042_	Lease: Whisman OWWO	Well # 5
Operator: Edmiston Oil Company	County: Rooks	115.05
Address: 125 N. Market - #1260	Well total depth	3540 feet
Wichita, Kansas 67202	Conductor Pipe:	
	Surface pipe 8 5/8 In	
	paramet paper of the annual paper.	1000
Aband. oil well, Gas well, Input we	11 x . SWD . D & A	
mana. ori weri, das weri, impae we	.11 <u>46</u> , 5WD, D & A	
Plugging contractor: Co Tools	т	i aonao#
rragging concractor. Co roots	u	rcense#
Address:		
Address:		·
Commons to always to House 40,00 B M. D.	4	
Company to plug at: Hour: 12:30 P.M. Day:	15 Month: September	Year: 1995
Plugging proposal received from: Dale Ma	У	
Company: Edmiston Oil Company	Phone:	
Were: Order 300 sxs 60/40 posmix - 10% ge	l and hulls.	
		Draw
		STATE CONFICEIVED
		STATE CORPORATION COMMISSION
		STATE CORPORATION COMMISSION
		SEP 2 5 100E
Plugging Proposal Peccived by: Work Poince		SEP 2 5 1995
Plugging Proposal Received by: Herb Deine	s	SEP 2 5 1995 9 - 25 - 95 CONSERVATION DWG
Plugging Proposal Received by: Herb Deine Plugging operations attended by agent? All	s	SEP 2 5 1995 9 - 25 - 95 CONSERVATION DWG
Plugging operations attended by agent? All	s [X], Part[], None[SEP 2 5 1995 9 - 25 - 95 CONSERVATION DIVISION Wichita, Kansas
	s [X], Part[], None[SEP 2 5 1995 9 - 25 - 95 CONSERVATION DIVISION Wichita, Kansas
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M. , Day: 15	[X], Part[], None[, Month:September	SEP 2 5 1995 9-25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w	s [X], Part[], None[, Month: September	SEP 2 5 1995 9-25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs.
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface to the squeezed to s	s [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement	SEP 2 5 1995 9-25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w	s [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement	SEP 2 5 1995 9-25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface to the squeezed to s	s [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying	SEP 2 5 1995 9-25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Perforated at 1483'.	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#.	s. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000#
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we represent at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs new hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing.	. [X], Part[], None[_, Month: September with 175 sxs. 4 1/2" to with 350 sxs Class A cement culled tubing in half trying met cement followed by 225 s city to TD was reached and	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom.
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' we Perforated at 1140' and squeezed to surface we scraper on tubing and got stuck at 1483'. Pronto production casing and pumped 75 sxs new hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B	SADAnhy.plug: Y	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom.
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X, CALC ,	SADAnhy.plug: Y	SEP 2 5 1995 9 25 95 9 25 95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_X_NO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25 95 9 25 95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom.
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25 95 9 25 95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_X_NO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M., Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_X_NO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M. , Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface w scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X I did Not[] observe the plugger	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_XNO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M. , Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface of scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs new hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X I did x Addition of loserve the plugger.	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_X_NO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M. , Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X I Gid V Add not[] observe the pluggents.	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_XNO
Plugging operations attended by agent? All Completed: Hour: 1:30 P.M. , Day: 15 Actual plugging report: 8 5/8" to 258' w Perforated at 1140' and squeezed to surface v scraper on tubing and got stuck at 1483'. P onto production casing and pumped 75 sxs ne hulls. Pressure began to develop after capa Max. P.S.I. 300#. S.I.P. 50#. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC , Plugged through TUBING , CASING X	SADAnhy.plug: Y. AND Anhy.plug: Y. Dakota plug: Y. Elevation:1904	SEP 2 5 1995 9 25-95 CONSERVATION DIVISION Wichita, Kansas , Year: 1995 3535' with 225 sxs. with 3% c.c. Running to get free. Tied sxs cement with 1000# hulls reached bottom. ES_XNO