TO: API Well Number: 15-163-00912-00-00 STATE CORPORATION COMMISSION **Spot:** CSENESW Sec/Twnshp/Rge: 22-10S-18W **CONSERVATION DIVISION - PLUGGING** 1650 feet from S Section Line, 2970 feet from E Section Line 130 SOUTH MARKET, SUITE 2078 Lease/Unit Name: EILERS B Well Number: 1 **WICHITA, KANSAS 67202 County: ROOKS** Total Vertical Depth: 3675 feet **Conductor Pipe: Size** feet: **Operator License No.: 32688** Surface Casing: Size 8.625 feet: <u>177</u> 150 SX CMT Op Name: H & R WELL SERVICES INC. **Production: Size 4.5** feet: 3668 **150 SX CMT** Address: 17509 COUNTY ROAD 14 19,44 Liner: Size feet: FT. MORGAN, CO 80701 Well Type: OIL **UIC Docket No: Date/Time to Plug:** 11/22/2001 9:00 AM Plug Co. Name: H & R WELL SERVICES INC. Plug Co. License No.: 32688 Proposal Rcvd. from: FRANK HUTTO Company: H & R WELL SERVICES INC. Phone: (970) 867-9007 Proposed Salt Section Top 1690'. Plugging | Casing log shows bad pipe. Method: Bad in Dakota Plugging Proposal Received By: HERB DEINES WitnessType: Plugging Operations 100% Witnessed (Complete) Date/Time Plugging Completed: 07/23/2001 4:00 PM **KCC Agent: RICHARD WILLIAMS Actual Plugging Report:** November 22, 2000 - Ran tubing to top of fish 1725'. Swift Services pumped 350 sxs 60/40 pozmix - 10% gel with 900# hulls. Shut in on vaccum. January 12, 2001 - Pumped total of 215 sxs with 500# hulls. At shut in cement 300' from surface. 7-25-01 January 25, 2001 - Allied ran wireline - found T.D. of 454'. 1 101 2 5 2001 July 6, 2001 - Swift Services pumped 40 sxs Swift Multi Density cement. Max. P.S.I. 800#. COMSERVATION DIVIDE Backside has hole in surface pipe. Will need to dig out and verify cement. July 23, 2001 - Dug out 8 5/8" x 4 1/2". Found no cement in surface pipe. Filled with 2 yards Redi-Mix. Remarks: 112200TUBING100%RW. 01122001CASING100%RW. 07062001CASING100%DH.07232001TOPPED OFF100%RW

Plugged through:

District: 04

Signed Richan Williams

(TECHNICIAN)

Form CP-2/3

involetu -

