KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

	
Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission V	Voods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-019-26961-0000	Lease Name & Well No.: Taylor 4-15
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	W2 NW NW
Settling Pit	Sec. 15 Twp. 32s R. West
Workover Pit Haul-Off Pit	754 Feet from North / South Line of Section
	402 Feet from East / V West Line of Section
	Chautauqua County
Was an artificial liner used?	
Self-Sealing Pit Abandonment procedure of pit:	RECEIVED
Self-Sealing Pit	•
Self-Sealing Pit Abandonment procedure of pit:	RECEIVED AUG 1,7 2003 KCC WICHITA
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	RECEIVED AUG 1,7 2003 KCC WICHITA
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is Agent	RECEIVED AUG 1,7 2003 KCC WICHITA
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	RECEIVED AUG 1,7 2003 KCC WICHITA
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	RECEIVED AUG 1,7 2003 KCC WICHITA for Layne Energy Operating, LLC (co.), a best of his /her knowledge and belief. Muse Jayuan
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	RECEIVED AUG 1,7 2003 KCC WICHITA for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief. Muse Jayuan
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	RECEIVED AUG 1,7 2003 KCC WICHITA for Layne Energy Operating, LLC (Co.), a best of his /her knowledge and belief. Muse Jayuan
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	RECEIVED AUG 1.7 2003 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his/her knowledge and belief. Mills Jaylor Signature of Applicant or Agent Lucyust 2009