KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission W	/oods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-125-31804-0000	Lease Name & Well No.: Bogart 12-16
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>W/2</u> _ <u>SW</u>
☐ Settling Pit ✓ Drilling Pit	Sec. 16 Twp. 33S R. 16 V East West
☐ Workover Pit ☐ Haul-Off Pit	1476 Feet from North / 🗸 South Line of Section
	504 Feet from ☐ East / ✓ West Line of Section
	Montgomery County
Was an artificial liner used? ☐ Yes ✔ No If no, how were the sides and bottom sealed to prevent downward migration of the prevent downward migration downward migrati	pit contents?
Self-Sealing Pit	RECFIVED
Self-Sealing Pit	RECEIVED SEP 2 1 2000
Self-Sealing Pit Abandonment procedure of pit:	RECEIVED SEP 2 1 2009
	RECEIVED SEP 2 1 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED SEP 2 1 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she isAgent	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and berief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and berief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	SEP 2 1 2009 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.