## STATE OF KANSAS STATE CORPORATION COMMISSION

٠ 🖔

Form CP-4

Make Required Affidavit Mail or Deliver Report to:		WELL PLUGGING RECORD									
Conservation Division State Corporation Commission					_						
212 No. Market Wichita, Kansas 67202		Rooks	Count	y. Sec. 19	Twp. 10 Rge.	$\frac{19}{(E)}$	$\underline{\hspace{1cm}}(\mathbf{w})^{\mathrm{X}}$				
NORTH	Location as "NE/CNWESWE" or footage from lines SW/SE/NW										
	- Lease Owner Al 11000										
		Lease Name H. Berland Well No. 5  Office Address Box 157 Hays, Kansas 67601  Character of Well (completed as Oil, Gas or Dry Hole)  Date well completed 19  Application for plugging filed 19  Application for plugging approved 19  Plugging commenced 11-20-71 19  Plugging completed 12-7-71 19									
	1										
	Application for										
	Plugging comm										
		Reason for abandonment of well or producing formation									
	Reason for aba										
	If a producing										
	Was permissio										
Locate well correctly on above Section Plat Name of Conservation Agent who su	menced?		es Mass	277		<u></u>	<del></del>				
Name of Conservation Agent who su	pervised plugging of th	is well 1	20 12336	- y	maral Davidad	3796	5 1/2				
Producing formation  Show depth and thickness of all wat	er oil and gas formatio	Depth to top	Botton	m	lotal Depth of	Well	reet				
-		113.									
OIL, CAS OR WATER RECO	RD\$		4			CASING RE	CORD				
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED	<del></del>				
				8 5/8	1621	None					
				5 1/2	3792	2001	4.54!				
						ļ					
3116',2920', 2 of <sup>83</sup> joints of	o 3750 and 5 sa 2714' and 2603' of 5 1/2" casin	. Worked pi g. Built a	pe loose rock b	e. Laid ridge and	down a tota. dumped 3						
	concrete at 70 i 3 yds readymi				bridge at 2	20					
Do alke rainose	I J yard I ( Logini	<u>x concrete</u>	00 5022								
					STATE	MECE	<u></u>				
					12-13-71	PORATIO	VED				
					COAL	JEO 12	COMACISCA				
		SIATE CORPORATION COMMISSION  12-13-71  DEC 13 1971  Wichita, Kansas									
	<del></del>	Wichita, Kansaş									
						- नवगड	<del>ας 13/Ο/Υ</del>				
				····	·						
	(If additions	al description is nece	ssary, use BAC	K of this sheet)		<del></del>	<del></del>				
Name of Plugging Contractor	Rockhold Engin	eering, Ind	) <u>.                                    </u>			<del></del>					
Address	Pi 0. Box 698						<u> </u>				
				The party of the same and the s							
	, co	UNTY OF	Barton		, \$s.						
James W. I					wner or operator)						
well, being first duly sworn on oath					tters berein contai	ned and the	log of the				
CATHY MILLER	•		<b>\</b> \ \ .	· / .		0]					
NOTARY PUBLIC Barton County, X	~ <b>9</b>	(Signature)		res W. 1	scrio	<u>a</u>					
The state of the s		<u>P.</u>	Ø. Box	698 Gre	at Bend, Kar	ısas 6'	7530				
SUBSCRIBED AND SWORM TO be	fore me this 9th	day of_	Decer	mber	(Address), 19	71					
The second state of the second			/	7.+1.	1 42 11	$\frac{1}{2}$					
<b>~</b>	20 30EF			Cally	Millon	Notar	y Public.				
My commission expires Sentemb	per 30, 1975			Catny	Miller	140suf j	, . <del></del>				

Form PO-214 Sheet 2 (12-47) 20M

## LOG OF WELL

SHEET NO.\_2\_

FORMATION	· Ab	TRUON	color ·	HARD OR SOFT	DEPTH CORES TAKEN	REMARKS
Clay & sand Shale & gravel Shale Shale & shells Shale & sand Sand	200 1 300 1 735 1	L00 L00 L00 L00 \$35 225				8-5/8" csg set at 1621' w/800 sax Lone Star Portland Bulk Cmt & 200# CC
Shale & shells Red Bed Shale Shale & shells Anhydrite	1390	350 110 75 37 28				5-1/2" csg set at 3792' w/100 sax Lone Star Bulk Cement
Shale	1650	10				ELEVATION:
Sandy shale Red bed & shale Shale Salt	1900   1 2000   1	100 120 100				2228 KB 2226 DF 2223 GL
Shale & lime Shale & shells	2070	70 95 65	•			TOPS:
Lime & shale Shale & lime Broken lime Brown shale & lime Lime Lime & shale Lime Lime & shale Lime Lime & shale Lime Lime & shale Chime Lime Conglomerate	2725 2965 3035 3110 3452 3492	70 50 30 85 75 130 75 240 75 340 273 273	STATI CONSE VII	CORPORATION CO.  RVATION DIVIS	D MMISSION ON	Topeka3229 Heebner3440 Lansing3477 Conglomerate.3715 Simpson3769 Arbuckle3791
TOTAL DEPTH 37961						
550' of c swabbed 2 9-27-48 Acidized	il, no w bbls o with 500	ator	- swabbe no water lons - to	per hour. ok acid a	t 350// pro	ours, hole filled up for five hours, ssure - swabbed
9-28-48 Swabbed h	ole down	(30	bbl oil)	- swappe	d 5 bbl o	1, no water per hour
an and and a	with 500 ack load well 1	i & s and	wabbed of swabbed	DOT OIT	THE THE HOLE	ook acid on vacuum - rs. swabbed 4.14 bbl