Form CP-4

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Inf on Completely
Make Required Aurdavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 No. Market

NORTH					
ļ					
	} }				
	ĺ	İ			
	!				
į					
		— —			
<u> </u>			ĺ		
1	!		! 		

WELL	PL	\mathbf{UG}	GING	REC	ORD
------	----	---------------	-------------	-----	-----

12 No. Market				- C ML	ומדוג ז'			
ichita, Kansas 67202 NORTH	Location as "NE	/CNWxSWx"	or footage from	n lines UNW	NE NE			
	Lease Owner	н. р. сс	llins		, k			
		Lease Name H.J. Vohys G#1 Well No						
	Office Address			T 1 1)				
	1		as Oil, Gas or	Dry Hole)		19		
	Date well compl	letedfled	* 4			19		
-	Application for p	_				19		
	Plugging comme		11/71			19		
1	Plugging comple	ted1	/14/71			19		
	Reason for aband	donment of wel	l or producing	formation del	oleted			
		11 . 1 . 1	3 3 4 62			19		
	If a producing v					re plugging was co		
Locate well correctly on above	was permission menced?		the Conserva	ttion Division of	its agents below	re plugging was co		
Section Plat e of Conservation Agent who sup	menced:	well l	lassey					
icing formation	D	epth to top	Bottom		Total Depth of	Well 3775 F		
depth and thickness of all water					_			
						ASING RECORD		
IL, GAS OR WATER RECOR	DS		,					
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	none		
	<u> </u>		ļ	8-5/8	172			
			 	4등!!	3755 !	789 '		
			 					
	 		 					
_								
			†					
Checked ho	nent or other plugs we set. le to 3512', sa 79', 1084', 990	anded to 34	25', dump	ed 4 sacks	of cement joints.	. Shot		
checked ho pipe at 11 Globe pump	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull	anded to 34 0', 898',	25', dump and 800',	ed 4 sacks	of cement joints.	. Shot		
checked ho pipe at 11 Globe pump	nent or other plugs we set. le to 3512', sa 79', 1084', 990	anded to 34 0', 898',	25', dump and 800',	ed 4 sacks	of cement joints.	. Shot		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800',	ed 4 sacks pulled 23	of cement joints.	. Shot		
checked ho pipe at 11 Globe pump	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800',	ed 4 sacks pulled 23	of cement joints.	. Shot		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	ed 4 sacks pulled 23	of cement joints.	. Shot		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	red 4 sacks pulled 23 70 cemen	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	red 4 sacks pulled 23 70 cemen	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	same and depth ed 4 sacks pulled 23 7, 70 cemen STATE COR 2-1-7	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	same and depth ed 4 sacks pulled 23 7, 70 cemen STATE COR 2-1-7	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	same and depth ed 4 sacks pulled 23 7, 70 cemen STATE COR 2-1-7	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898',	25', dump and 800', , 2 hulls	same and depth ed 4 sacks pulled 23 7, 70 cemen STATE COR 2-1-7	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac	anded to 34 0', 898', s, 20 gel	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE R 2-1-7 CONSERN	of cement joints. t, 8 gel,	. Shot turn		
checked ho pipe at 11 Globe pump plug loose PLUGGING C	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH	anded to 34 or 898', s, 20 gel oks of cem description is nee	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE R 2-1-7 CONSERN	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH	anded to 34 0', 898', s, 20 gel	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE R 2-1-7 CONSERN	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH	anded to 34 or 898', s, 20 gel oks of cem description is nee	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE R 2-1-7 CONSERN	of cement joints. t, 8 gel,	. Shot turn		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH	anded to 34 or 1, 898', s, 20 gel cks of cem description is need T (ASING	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE R 2-1-7 CONSERN	of cement joints. t, 8 gel, FCETVES PORATION COM	. Shot turn		
checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C Teess TE OF KANS	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASH	description is need. CANSAS	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 70 cemen STATE COR 2-1-7 CONSERN Vich owner) or (own	of cement joints. t, 8 gel, FCEIVES PORATION COMP. B1 1971 MATION DIVIS Kansas , ss.	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C TE OF KANS KANS L, being first duly sworm on oath	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI	description is need T (ASING). KANSAS	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 pulled 23 pulled 70 cemen STATE COR 2-1-7 CONSERN Vich owner) or (ownents, and matter	of cement joints. t, 8 gel, FCEIVES PORATION COMP. B1 1971 MATION DIVIS Kansas , ss.	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C ATE OF KANS I, being first duly sworm on oath	ment or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI	description is need T (ASING). KANSAS	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 pulled 23 pulled 70 cemen STATE COR 2-1-7 CONSERN Vich owner) or (ownents, and matter	of cement joints. t, 8 gel, FCEIVES PORATION COMP. B1 1971 MATION DIVIS Kansas , ss.	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C ATE OF KANS A to being first duly, sworm on oath we-described well as filed and the content of the co	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI SAS , COU NOEL J. KNIGH , says: That I have known at the same are true and set.	description is need TO ASING E. KANSAS OTHER OF THIT owledge of the ad correct. So	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23 pulled 23 pulled 70 cemen STATE COR 2-1-7 CONSERN Vich owner) or (ownents, and matter	of cement joints. t, 8 gel, FCEIVES PORATION COMP. B1 1971 MATION DIVIS Kansas , ss.	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C ATE OF KANS I, being first duly sworm on oath	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI SAS , COU NOEL J. KNIGH , says: That I have known at the same are true and set.	description is need T (ASING). KANSAS	25', dump and 800', 2 hulls ent.	same and depth seed 4 sacks pulled 23 , 70 cemen significant for this sheet shows and matter seems, and matter seems, and matter seems.	of cement joints. t, 8 gel, FCEIVES PORATION COM ATION DIVIS ATION DIVIS ATION DIVIS A ser or operator) s herein contain	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C TE OF KANS being first duly sworm on oath ve-described well as filed and the contractor of the contract	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI SAS , COU NOEL J. KNIGH , says: That I have known at the same are true and set.	description is need TO ASING E. KANSAS OTHER OF THIT owledge of the ad correct. So	25', dump and 800', 2 hulls ent.	same and depth ed 4 sacks pulled 23, 70 cemen size CONSERI Vich	of cement joints. t, 8 gel, FCEIVES PORATION COM ATION DIVIS ATION DIVIS ATION DIVIS A ser or operator) s herein contain	. Shot turn M/SSION		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C ATE OF KANS A to being first duly sworm on oath ve-described well as filed and the content of the con	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH KNIGH CHASH SAS , COU MOEL J KNIGH , says: That I have known at the same are true and	description is need to description is need. The content of the con	essary use BACK PULLING C	same and depth led 4 sacks pulled 23 for this sheet led 1 led 2 led 1 led 2 led 1 led 2 led 1 led 2 le	of cement joints. t, 8 gel, FCEIVE PORATION COMMITTEE KANSAS Address)	Shot turn MISSION TON TON		
Checked ho pipe at 11 Globe pump plug loose PLUGGING C PLUGGING C Tess ATE OF KANS I, being first duly, sworm on oath ve-described well as filed and the contract of the	nent or other plugs we set. le to 3512', sa 79', 1084', 990 ed 3 sacks hull and ran 50 sac OMPLETE. (If additional KNIGH CHASI SAS , COU MOEL J. KNIGH , says: That I have known at the same are true and and the same are true and the same a	description is need. The content of	essary use BACK PULLING C	same and depth ed 4 sacks pulled 23 pulled 23 pulled 23 pulled 23 pulled 27	of cement joints. t, 8 gel, FCEIVE PORATION COMMITTEE KANSAS Address)	Shot turn MISSION TON TON		