8-15 4-<u>041712</u>

	RATION COMMISSION					<u>9-53</u>
CONSERVATIO						
	N DIVISION - PLUG			<u>NW</u> /4 SE		
	ARKET, SUITE 2078		330	feet	from N se	ction line
WICHITA, KA	NSAS 67202		<u>3630</u>	feet	from E se	ction line
	•					
Operator li	cense# 31008		Lease:	Wilson	\B'	Well # <u>7</u>
Operator:	Paul Bowman Oil	Company	_ County	: Rooks		123.
	Вож 54			otal depth		
	801 Codell Road					
	Codell, Kansas 6	7630-0054	Surface pipe	8% Inch @		
Aband. oil	well <u>x</u> , Gas well	, Input	well, SW	D, D & A_		150 sxs.
Plugging co	ntractor: Alli	ed Cementing			License#_	-
Address:	Russell, Kansas	67665				
Company to p	plug at: Hour: 8:	00 A.M. Day:_	15 Month	: August	Yea	r <u>1995</u>
Plugging pro	oposal received f	rom: Paul :	Bowman			
	Bowman Oil Compan					
company:	Bownian OII Compan	<u></u>		Phone:		 .
						
		<u> </u>				
		· · · · · · · · · · · · · · · · · · ·				
	pposal Received by					
	pposal Received by					
Plugging ope	erations attended	by agent? A	ll[x], Part	[], None[1	
Plugging ope		by agent? A	ll[x], Part	[], None[1	
Plugging ope	erations attended Hour: 2:00 P.M.	by agent? A	ll[x], Part _, Month:	[], None[] , Yea:	r: 1995
Plugging ope Completed: Actual plugg	erations attended Hour: 2:00 P.M. ging report: R.I.H	by agent? A. , Day: 15 . with tubing	ll[X], Part _, Month: to 2300'. S	[], None[August], Year	r: <u>1995</u> th 50# hul
Plugging ope Completed: Actual plugg Eollowed wit	Hour: 2:00 P.M. ging report: R.I.H th 5 sxs gel, follo	by agent? A. , Day: 15 . with tubing owed with 50 s	ll[X], Part _, Month: _ to 2300'. s exs cement wit	[], None[August potted 50 sxs h 50# hulls.], Year cement with	r: 1995 th 50# hul ing to 100
Plugging ope Completed: Actual plugg Followed wit Spotted 50	Hour: 2:00 P.M. ying report: R.I.H h 5 sxs gel, follows cement with	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls t	ll[X], Part _, Month: _ to 2300'. s exs cement wit to circulate	[], None[August potted 50 sxs h 50# hulls. at surface.	cement with Pulled tub	r: 1995 th 50# hul ing to 100
Plugging operations of the Plugging operations of the Plugging	Hour: 2:00 P.M. ging report: R.I.H th 5 sxs gel, follo	by agent? A. , Day: 15 . with tubing bwed with 50 s 200# hulls to cement. Max.	ll[X], Part _, Month: _ to 2300'. S EXS cement wit to circulate P.S.I. 300#.	August potted 50 sxs h 50# hulls. at surface. S.I.P. 100#	cement with Pulled tub P.O.O.H.	th 50# hul ing to 100 with tubi
Plugging oper Completed: Actual plugg Followed wit Spotted 50 Squeezed cas	Hour: 2:00 P.M. Fing report: R.I.H Sing with 50 sxs cement with	by agent? A. , Day: 15 . with tubing bwed with 50 s 200# hulls to cement. Max.	ll[X], Part _, Month: _ to 2300'. S EXS cement wit to circulate P.S.I. 300#.	August potted 50 sxs h 50# hulls. at surface. S.I.P. 100#	cement with Pulled tub P.O.O.H. OO#. RECE	r: 1995 th 50# hul ing to 100 with tubi
Plugging operations of the Plugging operations of the Plugging	Hour: 2:00 P.M. Fing report: R.I.H Sing with 50 sxs cement with	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to	ll[X], Part _, Month: _ to 2300'. S EXS cement wit to circulate P.S.I. 300#.	August potted 50 sxs h 50# hulls. at surface. S.I.P. 100#	cement with Pulled tub P.O.O.H. OO#. RECE	th 50# hulling to 100 with tubi
Plugging operations of the Plugging operations of the Plugging	Hour: 2:00 P.M. Fing report: R.I.H Sing with 50 sxs cement with	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to	ll[X], Part _, Month: _ to 2300'. S EXS cement wit to circulate P.S.I. 300#.	August potted 50 sxs h 50# hulls. at surface. S.I.P. 100#	cement with Pulled tub P.O.O.H. OO#. RECE	r: 1995 th 50# hul ing to 100 with tubi
Plugging operations of the Plugging operations of the Plugging	Hour: 2:00 P.M. Fing report: R.I.H Sing with 50 sxs cement with	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to	ll[X], Part _, Month: _ to 2300'. S EXS cement wit to circulate P.S.I. 300#.	August potted 50 sxs h 50# hulls. at surface. S.I.P. 100#	cement with Pulled tub P.O.O.H. OO#. RECE	th 50# hulling to 100 with tubi
Plugging operations of the Plugging operations of the Plugging operation operation of the Plugging operation opera	Hour: 2:00 P.M. ging report: R.I.H th 5 sxs gel, follows sxs cement with sing with 50 sxs Squeezed 25 sxs E casing(in hole):	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to cement. Max. cement with 1	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	1995 th 50# hul ing to 100 with tubi HON COMMISSION 0 1995
Plugging operation of the Plugging operation operation of the Plugging operation operation of the Plugging operation opera	Hour: 2:00 P.M. ging report: R.I.H th 5 sxs gel, follows sxs cement with sing with 50 sxs Squeezed 25 sxs E casing(in hole):	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to cement. Max. cement with 1	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	1995 th 50# hul ing to 100 with tubi HON COMMISSION 0 1995
Plugging operation of the plugging operation operation of the plugging operation o	Hour: 2:00 P.M. Ingreport: R.I.H Sing report: With sing with 50 sxs of Squeezed 25 sxs	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to sement. Max. cement with : GOOD X X, CALC	ll[X], Part _, Month:	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	th 50# hulling to 100 with tubi
Plugging operation of the plugging operation operation of the plugging operation o	Hour: 2:00 P.M. Jing report: R.I.H. Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to sement. Max. cement with : GOOD X X, CALC	ll[X], Part _, Month:	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	th 50# hulling to 100 with tubi
Plugging operation of Squeezed cases 5/8" S.P. Remarks: Condition of Sottom pluggers	Hour: 2:00 P.M. Jing report: R.I.H. Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to the cement. Max. cement with GOOD X X, CALC _, CASING	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	th 50# hulling to 100 with tubi
Plugging operation of Bottom plugged through the plugged through t	Hour: 2:00 P.M. Hour: 2:00 P.M. Jing report: R.I.H. Sing systement with Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES Dugh TUBING X	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to the cement. Max. cement with GOOD X X, CALC _, CASING	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	Year cement wide Pulled tub P.O.O.H. OO#. REGEN ANSAS CORPORA AUG 3	th 50# hulling to 100 with tubing to 100 with tubing to 100 with tubing to 1995
Plugging operation of the plugging operation of the plugged through the plugged throug	Hour: 2:00 P.M. Hour: 2:00 P.M. Jing report: R.I.H. Sing systement with Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES Dugh TUBING X	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to the cement. Max. cement with GOOD X X, CALC _, CASING	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	real process of the p	th 50# hulling to 100 with tubing to 100 with tubing to 100 with tubing to 1995
Plugging operation of Bottom plugged through the plugged through t	Hour: 2:00 P.M. Hour: 2:00 P.M. Jing report: R.I.H. Sing systement with Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES Dugh TUBING X	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to the cement. Max. cement with GOOD X X, CALC _, CASING	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	real process of the p	th 50# hulling to 100 with tubing to 100 with tubing to 100 with tubing to 1995
Plugging operation of the plugging operation of the plugged through the plugged throug	Hour: 2:00 P.M. Hour: 2:00 P.M. Jing report: R.I.H. Sing systement with Sing with 50 sxs of Squeezed 25 sxs Casing(in hole): (in place): YES Dugh TUBING X	by agent? A. , Day: 15 . with tubing owed with 50 s 200# hulls to the cement. Max. cement with GOOD X X, CALC _, CASING	ll[X], Part _, Month: to 2300'. S EXS CEMENT WIT TO CITCULATE P.S.I. 300#. 100# hulls.	[], None[August potted 50 sxs h 50# hulls. at surface. S.I.P. 100# Max. P.S.I. 2 Kanhy.plug Dakota pl	real process of the p	th 50# hulling to 100 with tubi