

KCC OIL/GAS REGULATORY OFFICE

Date 8/24/09

- ( ) New Situation
- () Response to Request
- ( ) Follow-up

Operator license # 32204

API# 13-057-20040-00-00

Operator Redland Resources, Inc.

Address 6001 NW 23<sup>rd</sup> Street

Location NE-SE-SW, Sec 5, T25S, R23W

Oklahoma City, OK 73127

Lease Warner Well # 5-14

County Ford

Operator phone number 405-789-7104

Reason for Investigation: Company requested a witness to the Alternate II cementing job.

Problem: Alternate II cementing requirements have not been met.

Person(s) Contacted: David Hickman

Findings: 13 3/8" set @ 267' @ 225 sx cmt. 4 1/2" set @ 4941' @ 200 sx cmt. on primary cementing job. Log-Tech perforated 4 1/2" @ 765'. Quality oilwell cementing pumped 250 sx 60/40 por, 4% gel, with 3% cc added to the last 50 sx. Circulated 50 sx to the pit.

RECEIVED

SEP 14 2009

GPS-37.90147°N, 99.87304°W

photos taken KCC WICHITA

Action/Recommendations: None. Alternate II cementing requirements have been met.

- ( ) Lease Inspection
- ( ) Complaint
- () Field Report

By Eui Man Lam

Retain 1 copy Joint District Office  
 Send one copy Conservation Division

- ( ) RBDMS
- ( ) KGS
- ( ) District files
- ( ) TA program
- ( ) T-1 database
- ( ) Courthouse

