

15-051-00976-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

- M. B. Armer &

Lease Owner Pickrell Drilling Co. Inc Address 705 4th Natl. Bank Bldg
(Applicant) wichita.

Lease (Farm Name) FROELICH Well No. 1

Well Location NW NW NW Sec. 15 Twp. 12 S Rge. 16 (E)-(W)

County Ellis Field Name (if any) _____

Total Depth 3440 Oil _____ Gas _____ Dry Hole X

Was well log filed with application? No. If not, explain: _____

Will be filed with plugging report.

Date and hour plugging is desired to begin 3/18/50.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary) None.

Name of the person on the lease in charge of well for owner _____

Beal Burton Address 1717 Washington Great Bend, Mo.

Name of Plugging Contractor Pickrell Drilling Company, Inc.

Address Same as above.

Invoice covering assessment for plugging this well should be sent to

Same Address Same

and payment will be guaranteed by applicant.

PLUGGING
FILE SEC 15 T 12 R 16 W
BOOK PAGE 143 LINE 44

3-21-1950
21 1950

Ed. Schetz
Applicant or Acting Agent

Date 3/18/50



15-051-00976-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

March 21, 1950

IN REPLY PLEASE
REFER TO THIS
SUBJECT

Well No.	1
Lease	Proelich
Description	NW NW NW 15-12-16W
County	Ellis
File No.	113-114

Pickrell Drilling Company, Inc.
705 Fourth Nat'l Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR