## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## **CLOSURE OF SURFACE PIT**



Form CDP-4 April 2004 Form must be Typed

Operator Name: Bobcat Oilfield Service Inc	License Number 2005
20000.011101.0011101	License Number: 3895
Operator Address: 30805 Coldwater Rd. Louisburg, KS. 66053	
Contact Person: Bob Eberhart	Phone Number: ( 913 ) 837 - 2823
Permit Number (API No. if applicable): 15-107-24108-00-00	Lease Name & Well No.: Snyder 💥 TS 🧸 / 7
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	N2 _ N2 _ NE _ NE
Settling Pit	Sec. 8 Twp. 20 R. 23 ✓ East West
Workover Pit Haul-Off Pit	4470 Feet from North / South Line of Section
	660 Feet from 🗸 East / West Line of Section
	Linn
Date of closure: 8/16/09	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Use drilling mud	
	RECEUTE
	RECEIVED KANSAS CORPORATION COMMISSION
	CORPORATION COMMISSION
Abandonment procedure of pit:	NOV <b>0 9</b> 2009
	NOV 0 9 2009
Abandonment procedure of pit:	NOV <b>0 9</b> 2009
Abandonment procedure of pit:	NOV 0 9 2009
Abandonment procedure of pit:	NOV 0 9 2009
Abandonment procedure of pit:  Air dry and fill with dirt.	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc(Co.),
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc(Co.),
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc(Co.),
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc. (Co.), e best of his her knowledge and belief.
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the  Subscribed and sworn to me on this day of	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc. (Co.), e best of his her knowledge and belief.
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the  Subscribed and sworn to me on this day of	NOV 0 9 2009  CONSERVATION DIVISION  WICHITA, KS  Bobcat Oilfield Service, Inc. (Co.), e best of his her knowledge and belief.  Signature of Applicant or Agent  November , 2009
Abandonment procedure of pit:  Air dry and fill with dirt.  The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the  Subscribed and sworn to me on this day of	NOV 0 9 2009  CONSERVATION DIVISION WICHITA, KS  for Bobcat Oilfield Service, Inc. (Co.), e best of his her knowledge and belief.