Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

OPERATOR: License #: 30606

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

API No. 15 - 077-21635-000054

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

	Name: Murfin Drilling Company, Inc.				Spot Description: N2 N2 NW NW			
Address 1: 250 N. Water, Suite 300				W2-N2-NW-Sw Sec.21 Twp.31 S. R. 5 East ✓ West				
Address 2:				2,450 Feet from North / South Line of Section				
City: Wichita, State: Ks. Zip: 67202 +				660 Feet from East / West Line of Section				
Contact Person: Stan Froetschner Phone: (785) 483-5371				Footages Calculated from Nearest Outside Section Corner: NE NW SE SW				
								Type of Well: (Check one)
Water Supply Well Other: SWD Permit #:				Lease Name: Helen Well #: 1-21				
ENHR Permit#:	Gas S	torage Permit #:			Completed:	Well II.		
Is ACO-1 filed? Yes No If not, is well log attached? Yes No				The plugging proposal was approved on:(Date)				
Producing Formation(s): List			احت	by: Ste	ve Van Gieson	(KCC Dis	rict Agent's Name)	
				by: Steve Van Gieson (KCC District Agent's Name) Plugging Commenced: 9-23-09 Plugging Completed: 9-28-09				
								Deptil to
Show depth and thickness of	all water, oil and gas form	nations.				***************************************		
Oil, Gas or Water			Casing Record (Surface, Conductor & Production)					
Formation	Content	Casing	Size		Setting Depth	Pulled Out		
44.1.0			0.5/01		007			
The state of the s	1		8-5/8'	15 W - 26 .	267'	None		
	100 C / 100 PM		5-1/2"		4792'	3534	RECE	
W Kd. 0				*-i	100 x 1 7 1 x 2 th	1 Coent in mit	-delization of the	
							SFD .	
Describe in detail the manner	Joean At 194	1-	fluid was	placed and	the method or method	ds used in introducing	Canal	
	in which the well is plugged, state the character of the sacks of the	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce	tom), to (to t casin ment.,	op) for each g loose pulled	omega set. @3534',pulled up to 310' and	ed up to 800', p d circulataed 8	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu	in which the well is plugged, state the character of the sacks of the	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce	tom), to (to t casin ment.,	op) for each g loose pulled	omega set. @3534',pulled up to 310' and	ed up to 800', p d circulataed 8	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu	in which the well is plugged, state the character of the sacks of the	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce	tom), to (to t casin ment.,	op) for each g loose pulled	omega set. @3534',pulled up to 310' and	ed up to 800', p d circulataed 8	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu	in which the well is plugged, state the character of the sacks of the	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce	tom), to (to t casin ment.,	op) for each g loose pulled	omega set. @3534',pulled up to 310' and	ed up to 800', p d circulataed 8	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu	in which the well is plugged, state the character of the state the state the state that	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	t casin ment., est of c	g loose g louse pulled casing,	omega set. @3534',pulled up to 310' and	ed up to 800', pd d circulataed 8 aplete.	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface,	in which the well is plugged, state the character of the state the character of the state up to 600'. 60/40 pos, 4%	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	t casin ment., est of c	g loose pulled casing, Mike's	@3534',pulle @3534',pulle up to 310' and Plugging Com	ed up to 800', pd d circulataed 8 aplete.	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface,	in which the well is plugged, state the character of the state the character of the state up to 600'. 60/40 pos, 4%	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	tom), to (to t casin ment., est of c	g loose pulled casing, Mike's	©3534',pulle up to 310' and Plugging Con	ed up to 800', pd d circulataed 8 aplete.	oumped	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface, Plugging Contractor License # Address 1: P.O. Box 46	in which the well is plugged, state the character of the state the state that the state	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	tom), to (to t casin ment., est of c	g loose g loose pulled casing, Mike's	©3534',pulle up to 310' and Plugging Con	ed up to 800', pd circulataed 8 applete.	oumped 0 sxs.	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface, Plugging Contractor License # Address 1: P.O. Box 46	in which the well is plugged, state the character of the state the state the character of the state t	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	tom), to (to t casin ment., est of (g loose g loose pulled casing, Mike's	©3534',pulle up to 310' and Plugging Con	ed up to 800', pd circulataed 8 applete.	oumped 0 sxs.	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface, Plugging Contractor License # Address 1: P.O. Box 46 City: Chase Phone: (620) 938-294	in which the well is plugged, state the character of the state the state the character of the state t	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	tom), to (to t casin ment., est of (g loose g loose pulled casing, Mike's	©3534',pulle up to 310' and Plugging Com	ed up to 800', pd circulataed 8 applete.	oumped 0 sxs.	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, pu cement to surface, Plugging Contractor License # Address 1: P.O. Box 46 City: Chase Phone: (620) 938-294 Name of Party Responsible for	in which the well is plugged, state the character of imped 2 sacks of illed up to 600'. 60/40 pos, 4% 31529	ged, indicating where the mud of same depth placed from (both cement on top. Cur pumped 35 sxs. ce gel. Layed down re	tom), to (to t casin ment., est of (g loose pulled casing, Mike's	©3534',pulle up to 310' and Plugging Com	ed up to 800', pd circulataed 8 aplete. ge, Inc.	oumped 0 sxs. + 0467	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, purcement to surface, Plugging Contractor License # Address 1:P.O. Box 46 City:Chase Phone: (620)938-294 Name of Party Responsible for State of Kansas Mike Kelso	in which the well is plugged, state the character of imped 2 sacks of illed up to 600'. 60/40 pos, 4% 31529 7 Plugging Fees: Murfi County, (Print Name)	ged, indicating where the mud of same depth placed from (bott cement on top. Curpumped 35 sxs. cegel. Layed down remaining the company, in Drilling Company, in Rice	tom), to (to t casin ment., est of o	g loose pulled casing, Mike's 1	plug set. @3534',pulle up to 310' and Plugging Com Festing & Salva Isas	ed up to 800', pd circulataed 8 aplete. ge, Inc. zip: 67524	pumped 0 sxs. + 0467	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, purcement to surface, Plugging Contractor License # Address 1: P.O. Box 46 City: Chase Phone: (620) 938-29 Name of Party Responsible for State of Kansas Mike Kelso Deing first duly sworn on oath,	in which the well is plugged, state the character of imped 2 sacks of illed up to 600'. 60/40 pos, 4% 31529 The property of the character of illed up to 600'. 60/40 pos, 4% County, County	ged, indicating where the mud of same depth placed from (bott cement on top. Curpumped 35 sxs. cegel. Layed down remaining the company, in Drilling Company, in Rice	tom), to (to t casin ment., est of o	g loose pulled casing, Mike's 1	plug set. @3534',pulle up to 310' and Plugging Com Festing & Salva Isas	ed up to 800', pd circulataed 8 aplete. ge, Inc. zip: 67524	pumped 0 sxs. + 0467	
Describe in detail the manner cement or other plugs were us Set BP @4580', du 35 sxs. cement, purcement to surface, Plugging Contractor License # Address 1:P.O. Box 46 City:Chase Phone: (620)938-294 Name of Party Responsible for State of Kansas Mike Kelso	in which the well is plugged, state the character of imped 2 sacks of illed up to 600'. 60/40 pos, 4% 31529 7 Hugging Fees: Murfi County, (Print Name) says: That I have knowled so help me God.	ged, indicating where the mud of same depth placed from (bott cement on top. Curpumped 35 sxs. cegel. Layed down remaining the company, in Drilling Company, in Rice	tom), to (to t casin ment., est of o	g loose pulled casing, Mike's 1	plug set. @3534',pulle up to 310' and Plugging Com Festing & Salva Isas	ed up to 800', pd circulataed 8 aplete. ge, Inc. zip: 67524	pumped 0 sxs. + 0467	