

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water) 212 N. Market 500 Insurance Bldg. WICHITA, KANSAS 67202

VERBAL PERMIT FORM (To Be Filed By Plugging Agent) Wichita, Kansas

J. Lewis Brock Administrator 500 Insurance Building Wichita, Kansas 67202

Mr. Roy Cook of Imperial Oil Company, has this date requested permission to plug the following described well: Mr. Cook guarantees payment of the plugging fee. Operator's full Name: Imperial Oil Company, Complete Address: 780 4th National Bank Bldg., Wichita, Kansas. Lease Name: Biden Well No. 1 Location: CE/2-NE-SE Sec. 1 Twp. 10 Rge. (E)(W) 22 County: Graham Total Depth 3936:011 Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209!8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675!. Circulate hole with heavy mud. Pull DP to 900! and displace 100 Sx. cement thru DP. Pull DP to 180! and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40! with ½ sack hulls and 10 Sx. cement to bottom of cellar.	Dear S	Sir:		•	
MrCook	Mr.	Roy Cook	of Imper	ial Oil Company,	has this
Complete Address: 780 4th National Bank Bldg., Wichita, Kansas. Lease Name: Biden Well No. 1 Location: CE/2-NE-SE Sec. 1 Twp. 10 Rge. (E)(W)22 County: Graham Total Depth 3936'Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209'-8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with \(\frac{1}{2} \) sack hulls and 10 Sx. cement to bottom	date r	equested permi	ssion to plug the	following describe	d well:
Complete Address: 780 4th National Bank Bldg., Wichita, Kansas. Lease Name: Biden Well No. 1 Location: CE/2-NE-SE Sec. 1 Twp. 10 Rge. (E) (W) 22 County: Graham Total Depth 3936' Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209'-8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to bottom	Mr.	Cook	guarante	es payment of the p	olugging fee.
Lease Name: Biden Well No. 1 Location: CE/2-NE-SE Sec.1 Twp. 10 Rge. (E)(W)22 County: Graham Total Depth 3936: Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209:-8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to bottom	Operat	or's full Name	: Imperial Oil Co	ompany,	
County: Graham Total Depth 3936: Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209:-8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with \(\frac{1}{2}\) sack hulls and 10 Sx. cement to bottom	Comple	te Address:	780 4th Nations	ıl Bank Bldg., Wichi	ita, Kansas.
Graham Total Depth 3936'Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Cook was instructed to plug the well as follows: 209'-8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to bottom	Lease	Name:	Biden	Well No	<u> </u>
Gas WellInput WellSWD WellD & A _X _Lost Hole	Locati	on:	CE/2-NE-SE	Sec. <u>l</u> Twp. <u>lO</u> Rg	e(E)(W) <u>22</u>
Mr. Cook was instructed to plug the well as follows: 209'8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to bottom	County	•	Graham	Total Depth3936	Oil Well
209'8 5/8" Surface casing, cement circulated with 185 Sx. Top of Dakota section @ 675'. Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with ½ sack hulls and 10 Sx. cement to bottom	Gas We	11Input W	ellSWD Well_	D & A X Los	t Hole
Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with $\frac{1}{2}$ sack hulls and 10 Sx. cement to bottom	Mr	Cook	was instru	cted to plug the we	ll as follows:
Circulate hole with heavy mud. Pull DP to 900' and displace 100 Sx. cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with $\frac{1}{2}$ sack hulls and 10 Sx. cement to bottom	20918	5/8" Surface	casing, cement ci	rculated with 185 S	Sx.
cement thru DP. Pull DP to 180' and displace 20 Sx. cement thru DP. Pull Dp. set bridge @ 40' with \frac{1}{2} sack hulls and 10 Sx. cement to bottom	Top of	Dakota section	@ 675'• 		
Pull Do. set bridge @ 40' with \(\frac{1}{2}\) sack hulls and 10 Sx. cement to bottom	Circula	te hole with h	eavy mud. Pull D	P to 900' and displ	ace 100^{-5} x.
or Certar.	PuII Do	<u>. set bridge @</u>	DP to 180' and d	isplace 20 ^S x. ceme hulls and 10 Sx. ce	nt thru DP.
	OT COLL				

Very truly yours,

Conservation Division Agent