9-18 . 4-<u>032093</u>

TO:	API Number: 15-065-21,521
STATE CORPORATION COMMISSION	100'NE of 5 <u>c sw nw</u> /4 sec. 9, 10s, 24 w
CONSERVATION DIVISION - PLUGGING	
130 SOUTH MARKET, SUITE 2078	3400 feet from S section line
WICHITA, KANSAS 67202	4520 feet from E section line
,, , , , , , , , , , , , , , , , , , ,	
Operator license#_4767_	Lease: Denio "P" Well # 5
Operator: Ritchie Exploration, Inc.	County: Graham
	Well total depth 4130 fee
Address: 125 N. Market	well total depth 120 1ee
Suite #1000	
Wichita, Kansas 67202	Surface pipe 8% Inch @ 209 fee
Aband. oil well $\underline{\mathbf{x}}$, Gas well $\underline{}$, Input well	, SWD, D & A
Plugging contractor: Mike's Testing & Salva	ige License# 31529
Address: Chase, Kansas 67525	
 .	
Company to plug at: Hour: P.M. Day: 18	Month: September Year: 1995
Plugging proposal received from: Manny	
Company: Mike's Testing & Salvage	Phone:
Were:Order 225 sxs 60/40 pozmix - 10%	gel - 500# hulls.
Allied Cement Company.	
Order sand and 4 sxs comment ceme	ent.
•	·
	STATE CORPORATION COMMISSION
	COMMISSION COMMISSION
	200 0 0
	35r 2 5 1995
	CONSERVATION DU 1995
and the second configuration of the second configuration o	
Plugging Proposal Received by: <u>Carl Good</u> Plugging operations attended by agent? All[x], Part[], None[]
Completed: Hour: 1:30 P.M., Day: 18, Month	n: September , Year: 1995
0 F/01 mak at 2001 an	with 175 avg 4 1/2" set at 4128' with 2
Actual plugging report: 8 5/8" set at 209' cv sxs. Prod. Perfs at 3856' - 4057'. PBTD 4077	NO WILLIAM TO BASE TALE SEC OF TARE WILLIAM
sxs. Prod. Perfs at 3856' - 4057'. PBTD 4077	Sand back to sove with a sas common come
on sand with bailer. First shot at 2250' -	second shot recovered 1550 of # 1/2 casta
Mixed and pumped down 4 1/2" 80 sxs cement b	lend with 200# hulls to 2250. With 500# P.S.
Pulled pipe to 150' circulated cement to surfa	ice with 40 sxs cement blend, into cellar. La
down casing. Hole remained full of cement.	Plug completed.
Remarks:	
Condition of casing(in hole): GOOD Ba	AD Anhy.plug: YES NO
Pattern mineral mineral VEC CALC	NO Dakota plug: YES , NO
Plugged through TUBING, CASING	Elevation:
India & Add hot lobserve the plugging	ng. Carl Goodrow
India 6 1 Cd a not[] observe the pluggin	ng. Carl Soodious (agent)
India () Cald not [] observe the pluggin	ng. Carl Soudious (agent) Form CP-2/3
India [6] Cd d hot[] observe the plugging [6]	ng. Carl Soudious (agent) Form CP-2/3
INDICATE $\frac{10-6-95}{1(31.77)}$	ng. Carl Goodious (agent) Form CP-2/3
Plugged through TUBING, CASING Indit(0 1 Cd d hot[] observe the plugging to th	ng. Carl Doodier (agent) Form CP-2/3