Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4
April 2004
Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: EOG Resources, Inc.	License Number: 5278
Operator Address: 3817 NW Expressway #500, Oklahoma City, OK 73112	
Contact Person: Sheila Rogers	Phone Number: (405) 246 - 3236
Permit Number (API No. if applicable): 15-189-22674-00-00	Lease Name & Well No.: Cullison 28 #4
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NW - NW - NE</u>
Settling Pit Drilling Pit	Sec. 28 Twp. 31 R. 35 East West
Workover Pit ✓ Haul-Off Pit	330' Feet from North / South Line of Section
	2310' Feet from East / West Line of Section
	<u>Stevens</u> County
Date of closure: 04/24/2009 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Native muds and clays.	
	pit contents?
	RECEIVED
Native muds and clays. Abandonment procedure of pit:	RECEIVED
Native muds and clays.	RECEIVED JUN 2 2 2009
Native muds and clays. Abandonment procedure of pit:	RECEIVED
Native muds and clays. Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED JUN 2 2 2009 KCC WICHITA forEOG Resources, Inc(Co.),
Native muds and clays. Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED JUN 2 2 2000 KCC WICHITA forEOG Resources, Inc(Co.),
Native muds and clays. Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED JUN 2 2 2000 KCC WICHITA forEOG Resources, Inc(Co.),
Native muds and clays. Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED JUN 2 2 2000 KCC WICHITA forEOG Resources, Inc(Co.),
Native muds and clays. Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Applicant	RECEIVED JUN 2 2 2000 KCC WICHITA forEOG Resources, Inc(Co.),