STATE OF KANSAS
STATE CORPORATION COMMISSION
200 Colorado Derby Bldg,
Wichita, Kansas 67202

Form CP-4 Rev. 12-15-80

WELL PLUGGING RECORD

.	Location a	as in qua	rters o	SEC. r footage NE/4	from lines:	S RGE. 18 NOW W
				etroleum (
•	Lease Name					No. 2
					end, Kansas 6	
						lole): Oil
	Application	m for nli	oging :	filed (June 4, 1941	.00
	Plugging	ommonad	reerrie .	rried (October 15, 19	82
	Plussing of	ompleted_		N	November 8; 19	82
					November 10, 1	
Locate Well	keason for	abandoni			roducing forma	tion
correctly on above				pleted		
Section Platt.						ision or it's
_	Agent's be					
me of Conservation Age	ent who superv	ised plug	ging of	this well	l <u>Gilbert Sc</u>	heck .
oducing formation	Arbuckle	Depth to	top3	3731 bot t	t om 3377' T .	D. <u>3377'</u>
w depth and thickness	s of all water	, oil and	gas fo	ormations.		
L, GAS OR WATER RECORD	OS			:		Casing Record
rmation	Content	From	То	Size	Put in	Pulled Out
Surface	Water	0'	1145'	8 5/8"	1145'	-0-
Production	Oil & Wtr	0'	3373'	5 1/2"	3373'	-0-
			ļ	 		
feet for ea	e method or med l, state the cl ach plug set.	thods use haracter MIRU Si	d in in of same uperior	troducing and depth WS. Ran	it into the ho placed, from 109 its 2 3/8	old. If cement feet
other plugs were used feet for ea 3359'. Conn Hallib to collowed by 1 1/2 BW. BFW. Pulled 50 jts to 2 BFW. Max pressulls, 210 sx 50-50 Patate plugger on loca	t method or method, state the clack plug set. o tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea	thods use haracter MIRU Si 5 BFW. 1 ts tbg us mpd 125 s H w/balar 1 & 3% Ca	d in in of same uperior Pmpd 25 to 30 sx 50-5 ace of acl. M	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix v thg. Conn ax press-	it into the home placed, from 109 jts 2 3/8 Pozmix w/4% go 17 sx go 16 sy/4% go 8 5/8" csg	old. If cement feet "TA tbg to cel & 3% CaCl cllowed by 8 CaCl followed c & pmpd 2 sx cin @ 300 PSI
other plugs were used feet for ea 3359'. Conn Hallib to followed by 1 1/2 BW. BFW. Pulled 50 jts to by 2 BFW. Max pressualls, 210 sx 50-50 PState plugger on loca	t method or method, state the clack plug set. o tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea	thods use haracter MIRU Si 5 BFW. 1 ts tbg us mpd 125 s H w/balar 1 & 3% Ca	d in in of same uperior Pmpd 25 to 30 sx 50-5 ace of acl. M	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix v thg. Conn ax press-	it into the home placed, from 109 jts 2 3/8 Pozmix w/4% go 17 sx go 16 sy/4% go 8 5/8" csg	old. If cement feet "TA tbg to cel & 3% CaCl cllowed by 8 CaCl followed c & pmpd 2 sx cin @ 300 PSI
other plugs were used feet for ea 3359'. Conn Hallib t followed by 1 1/2 BW. BFW. Pulled 50 jts t by 2 BFW. Max press- hulls, 210 sx 50-50 P State plugger on loca plate. Well P&A, 11-	t method or method, state the clack plug set. o tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82.	thods use haracter of MIRU So 5 BFW. I ts tbg up mpd 125 s H w/balar 1 & 3% Ca se Hallib is necess iburton S	d in in of same uperior Pmpd 25 to 30 sx 50-5 ace of acl. Management of Sary, use Services	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix v thg. Conn ax press- erior WS.	it into the hon placed, from 109 its 2 3/8 Pozmix w/4% gl 17 sx gel for 17 sx gel for 18 5/8" csg 1000 PSI, shut	old. If cement feet "TA tbg to gel & 3% CaCl bllowed by 8 CaCl followed c & pmpd 2 sx in @ 300 PSI
other plugs were used feet for ea 3359'. Conn Hallib t followed by 1 1/2 BW. BFW. Pulled 50 jts t by 2 BFW. Max press- hulls, 210 sx 50-50 P State plugger on loca plate. Well P&A, 11- (If additiona me of Plugging Contrac	t method or method, state the clack plug set. o tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82.	thods use haracter of MIRU So 5 BFW. I ts tbg us mpd 125 s H w/balar 1 & 3% Ca se Hallib	d in in of same uperior Pmpd 25 to 30 sx 50-5 ace of acl. Management of Sary, use Services	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix v thg. Conn ax press- erior WS.	it into the hon placed, from 109 its 2 3/8 Pozmix w/4% gl 17 sx gel for 17 sx gel for 18 5/8" csg 1000 PSI, shut	old. If cement feet "TA tbg to cel & 3% CaCl cllowed by 8 CaCl followed c & pmpd 2 sx cin @ 300 PSI
other plugs were used feet for ea 3359'. Conn Hallib t followed by 1 1/2 BW. BFW. Pulled 50 its t by 2 BFW. Max press- hulls, 210 sx 50-50 P State plugger on loca plate. Well P&A, 11- (If additiona ne of Plugging Contrac ATE OF KANSAS J. R. MILLER ove-described well, be ests, statements, and me and and that the agree	t method or method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82. COUNTY OF ing first duly	thods use haracter of MIRU State of BFW. Its tbg up mpd 125 state of the Mirotal	d in in of same uperior Pmpd 25 to 30 sx 50-5 nce of acl. Management of Superior Cansas ee of own oath, i and the same of the contract of the	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix v thg. Conn ax press- erior WS. se BACK of s ,ss. wher) or (c says: The	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% gel 17 sx gel for 17 sx gel for 18 5/8" csg 1000 PSI, shut To cut off control of this sheet) owner or opera	old. If cement feet "TA tbg to gel & 3% CaCl bllowed by 8 CaCl followed & pmpd 2 sx in @ 300 PSI. sg & weld on
other plugs were used feet for ea 3359'. Conn Hallib to followed by 1 1/2 BW. BFW. Pulled 50 its to 2 BFW. Max pressbulls, 210 sx 50-50 Postate plugger on local plate. Well P&A, 11- (If additional to a state of Plugging Contract of Contract of Plugging Contrac	t method or method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82. COUNTY OF ing first duly	thods use haracter of MIRU State of BFW. Its tbg up mpd 125 state of the Mirotal	d in in of same uperior Pmpd 25 to 30 sx 50-5 nce of acl. Management of Superior Cansas ee of own oath, i and the same of the contract of the	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix w thg. Conn ax press- erior WS. se BACK of s ,ss. wher) or (says: The ne log of to me God. ature)	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% gel 17 sx gel for 17 sx gel for 17 shut 1000 PSI, shut 1	old. If cement feet "TA tbg to cel & 3% CaCl cellowed by 8 CaCl followed & pmpd 2 sx in @ 300 PSI. sg & weld on tor) of the ledge of the ribed well as
other plugs were used feet for ea 3359'. Conn Hallib t followed by 1 1/2 BW. BFW. Pulled 50 its t by 2 BFW. Max press- pulls, 210 sx 50-50 P State plugger on loca plate. Well P&A, ll- (If additional the of Plugging Contract TE OF KANSAS J. R. MILLER ts, statements, and me ed and that the same AND	t method or method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82. COUNTY OF ing first duly	thods use haracter of MIRU State of BFW. Its tbg up mpd 125 state of the Mirotal	d in in of same uperior Pmpd 25 to 30 sx 50-5 nce of aCl. Mos Superior Rary, use Service: Kansas	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix w thg. Conn ax press- erior WS. se BACK of s ,ss. wher) or (says: The ne log of to me God. ature)	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% gel 17 sx gel for 17 sx gel for 17 shut 1000 PSI, shut 1	old. If cement feet "TA tbg to cel & 3% CaCl cellowed by 8 CaCl followed & pmpd 2 sx in @ 300 PSI. sg & weld on tor) of the ledge of the ribed well as
other plugs were used feet for ea 3359'. Conn Hallib the followed by 1 1/2 BW. BFW. Pulled 50 its the by 2 BFW. Max presshulls, 210 sx 50-50 P. State plugger on local plate. Well P&A, lled the followed by 1 1/2 BW. BFW. Pulled 50 its the by 2 BFW. Max presshulls, 210 sx 50-50 P. State plugger on local plate. Well P&A, lled the followed by the following contract of the following contract in the following c	t method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO tozmix w/4% getion. Relea 10-82. I description tor Hall Grea COUNTY OF ing first duly atters herein are true and co	is necessiburton St Bend, K BARTON (employer sworn or contained correct.	d in in of same uperior Pmpd 25 to 30 sx 50-5 nce of aCl. Mo Superior Reprise Service: Kansas	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix withg. Conn ax press—erior WS. see BACK of s ,ss. wher) or (of says: The log of the l	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% gi 17 sx gel for y/4% gel & 3% to 8 5/8" csg 1000 PSI, shut To cut off cout of co	tor) of the ledge of the ribed well as Office Super od, Kansas 6753
other plugs were used feet for ea 3359'. Conn Hallib t followed by 1 1/2 BW. BFW. Pulled 50 its t by 2 BFW. Max press- pulls, 210 sx 50-50 P State plugger on loca plate. Well P&A, ll- (If additional the of Plugging Contract TE OF KANSAS J. R. MILLER ts, statements, and me ed and that the same AND	t method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO tozmix w/4% getion. Relea 10-82. I description tor Hall Grea COUNTY OF ing first duly atters herein are true and co	is necessiburton St Bend, K BARTON (employer sworn or contained correct.	d in in of same uperior Pmpd 25 to 30 sx 50-5 nce of aCl. Mo Superior Reprise Service: Kansas	troducing and depth WS. Ran sx 50-50 48'. Pmpx 0 Pozmix withg. Conn ax press—erior WS. see BACK of s ,ss. wher) or (of says: The log of the l	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% go 17 sx gol for y/4% gol & 3% to 8 5/8" csg 1000 PSI, shut To cut off cout of cou	tor) of the ledge of the ribed well as Office Superad, Kansas 675:
other plugs were used feet for ea 359'. Conn Hallib to Collowed by 1 1/2 BW. SFW. Pulled 50 its to 2 BFW. Max pressuals, 210 sx 50-50 Potate plugger on local plate. Well P&A, 11- (If additional e of Plugging Contract Fe KANSAS J. R. MILLER ve-described well, bests, statements, and meed and that the same and th	t method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO tozmix w/4% getion. Relea 10-82. I description tor Hall Grea COUNTY OF ing first duly atters herein are true and co	is necessiburton St Bend, K BARTON (employer sworn or contained correct.	d in in of same uperior Pmpd 25 to 30 Sx 50-5 nce of aCl. March Superior Reprices (Sansas See of own oath, and the So help (Signal 11th)	se BACK of says: The log of stare of STATE	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% go 17 sx gel for y/4% gel & 3% to 8 5/8" csg 1000 PSI, shut To cut off compart I have known the above-descent of the compart I have known t	tor) of the ledge of the ribed well as Office Super od, Kansas 6753
other plugs were used feet for ea 3359'. Conn Hallib the followed by 1 1/2 BW. BFW. Pulled 50 its the power of the plugger on local plate. Well P&A, 11— (If additional the power of the plugging Contract of the plugging Contract of the power of the po	t method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO tozmix w/4% getion. Relea 10-82. I description tor Hall Grea COUNTY OF ing first duly atters herein are true and co	is necessiburton St Bend, K BARTON (employed sworn or contained correct.	d in in of same uperior Pmpd 25 to 30 Sx 50-5 nce of aCl. March Superior Reprices (Sansas See of own oath, and the So help (Signal 11th)	se BACK of says: The log of stars of STATE	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% gel 17 sx gel for y/4% gel 8 3% to 8 5/8" csg 1000 PSI, shut To cut off compared in this sheet) this sheet) owner or operated in the above-descent at I have known the above-descent at I h	tor) of the ledge of the ribed well as Office Super od, Kansas 6753 19 82 SNION TA tog to feet 18" TA tog to come feet 3" TA tog to come feet 19 82 SSION Ty Public.
d was placed and the ther plugs were used feet for ea 59'. Conn Hallib to the pluged by 1 1/2 BW. W. Pulled 50 its to 2 BFW. Max pressible, 210 sx 50-50 Pate plugger on loca ate. Well P&A, llace of Plugging Contract of Plugging Contract E OF KANSAS J. R. MILLER e-described well, being statements, and mand that the same at and that the same at and that the same at another plugging Contract of Plugging Cont	t method or method, state the clack plug set. to tbg & pump Pulled 10 j bg to 1512'-p 400 PSI. COO OZMIX W/4% getion. Relea 10-82. COUNTY OF ing first duly atters herein are true and co	is necessiburton St Bend, K BARTON (employed sworn or contained correct.	d in in of same uperior Pmpd 25 to 30 Sx 50-5 nce of aCl. March Superior Reprices (Sansas See of own oath, and the So help (Signal 11th)	se BACK of says: The log of stars of STATE	it into the hor placed, from 109 its 2 3/8 Pozmix w/4% go 17 sx gel for y/4% gel & 3% to 8 5/8" csg 1000 PSI, shut To cut off compart I have known the above-descent of the compart I have known t	tor) of the ledge of the ribed well as Office Sured, Kansas 67 19 82 SSION TA tog to fee fee fee fee fee fee fee fee fee fe

Wichita Kansas

DAILY REPORT DETAILED

3064

L	EASE	HUGH	WELL NO2
•			DF ELEV. 1872
D	ATE	TOTAL DEPTH	NATURE OF WORK PERFORMED
MAY	1941		
14		314	Location 990 ft. from the east and 660 ft. from the north, S/2 NE/4 14-11-18W Ellis County, Kansas. Digging pits and
	· · · · · · · · · · · · · · · · · · ·		cellar and moving in Rotary Rig #13. Rigged up and SPUDDED.
15	:	1150	Drilling Anhydrite. Top Anhydrite 1138.
16		1150	Set the 8 5/8" 32# 8 Thd LW casing "B" condition at 1145
			with 350 sacks Dewey fibre cement. Plug went to 1120 at 2:05 a.m. Good cement returns to cellar. WOCTS.
17		· 115 0	WOCTS.
18	•	1944	Drilling shale and lime.
19		2357	Drilling shale and shells.
20		2714	Drilling shale and shells.
21	•	2862	Drilling shale and shells.
22		2902	Lost circulation at 2902 and pipe stuck 7 jts. off bottom. Circulated oil and got loose ok.
23		2995	Drilling lime.
24		3126	Coring lime. Top Kansas City 3064.
25		3260	Drilling lime. Drilled soft 3121-23 w/ good saturation in samples. Cored 3123-31 for 8 ft. recovery of hard dense
			lime, top 1 ft. was stained.
26			Drilling lime.
27		3375	Top Arbuckle 3373. Saturation in samples. Set the 5 1/2" 14# 8 Thd SS casing "A" condition at 3373 with 200 sacks
	•		Dewey fibre cement. Plug went to 3336 at 3:48 p.m. the 27th
			WOCTS. Tear down rotary and move out.
28		3375	WOCTS.
29		3375	Moved in Cardwell Unit #2, rigged up and bailing mud.
30		3375	Drilled cement to shoe and loaded hole with 500 ft. water
			and drilled the shoe at 7:30 p.m. Had 630 ft. OIH in 1/2
		•	hour. Bailing water all the while. 1356 ft. OIH in $1\frac{1}{4}$
31		gana .	hrs. 2592 ft. in 3 hrs.
31		3377	Started coring at 11 p.m. on the 30th. Cored 3375-77 for
			recovery of cement and porous saturated dolomite. Had
			2930 ft. OIH in 5 3/4 hrs. Swabbed down to 1000 ft. from
			top and lst. hr. made 31 bbls. oil no water. Swabbed
			down to 1200 ft. from top and 1st hr. made 43 bbls. 2nd
		•	hour made 42 bbls. Hole clean, tore down tools and moved
JIME	1941		out. Ran 2 1/2" tubing and rods. Ready set pump unit.
2-3) *** **	3377	Set numning unit and wait on State Non to take natorti-?
4		3377 3377	Set pumping unit and wait on State Man to take potential. OFFICIAL STATE ECHO-METER INITIAL POTENTIAL 6,634 bbls.
-		0011	oil, no water. Corr. gravity 30.5 Effective 6-4-41.
			FINAL REPORT.
	• •		A ALIGNA TION CITY



OCT 1 8 1982

CONSERVATION DIVISION Wichita, Kansas