STATE OF KANSAS STATE CORPORATION COMMISSION	WELL PLUGGING RECORD K.A.R82-3-117	API NUMBER 15-179-20593-000		
200 Colorado Derby Building Wichita, Kansas 67202		LEASE NAME <u>Martin</u>		
Wichila, Kansas evass	TYPE OR PRINT	WELL NUMBER 3		
	NOTICE: Fill out completely and return to Cons. Div.	1980 Ft. from S Section Line		
	office within 30 days.	1650 Ft. from E Section Line		
		E/2 NW SE		
LEASE OPERATOR Petroleum Prop		SEC. 16 TWP. 10 RGE. 26W (E) or (W)		
ADDRESS 155 N. Market, #1010	0, Wichita, Kansas 67202- <u>18</u> 24	COUNTY Sheridan		
PHONE# (316 265-3351 OPERA	ATORS LICENSE NO. 31142	Date Well Completed		
Character of Well Oil	Plugging Commenced 6-10-93			
(OII, Gas, D&A, SWD, Input, Wa		Plugging Completed 6-11-93		
(UII, Gas, Dan, SHD, THPUT) "	and on	(date)		
The plugging proposal was appr	-0/80 Ou	(date)		
υγ	Carl Goodrow	(KCC District Agent's Name).		
is ACO-1 filed?	f not, is woll log attached?			
Draduoing Formation	Depth to Top	BottomT.D4075'		
show don'th and thickness of a	ll water, oll and gas formatio	ons.		
Show depth and thickness of al	II water, oll and gas formatio	ASING RECORD		
Show depth and thickness of al	From To Sizo	ASING RECORD Put in Pulled out		
Show depth and thickness of al	From To Sizo 8-5/8"	Put in Pulled out 244 none		
OIL, GAS OR WATER RECORDS Formation Content	From To Sizo	ASING RECORD Put in Pulled out		
OIL, GAS OR WATER RECORDS Formation Content	Water, oll and gas formation	Put in Pulled out 244' none 4037' 1121'		
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner	From To Sizo	Put in Pulled out 244' none. 4037' 1121' I, Indicating where the mud fluid wa		
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner	From To Sizo	Put in Pulled out 244' none. 4037' 1121' I, Indicating where the mud fluid wa		
OIL, GAS OR WATER RECORDS Formation Content Describe in detail the manner placed and the method or method are used, state the charace	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged nods used in introducing it in the of same and depth place.	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want of the hole. If coment or other plugged, from feet to feet each set of the Shot Dipe (2200', 1800', 1600', 1600')		
Formation Content Describe in detail the manner placed and the method or method or Plugged off bottom with september 25 sacks cement @Io	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and used in introducing it in the depth place and to 3800' and 4 sacks cemes and to 2200'. Shot pipe @13	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumperacks cement to surface. Pulled rest		
Formation Content Describe in detail the manner placed and the method or method or pumped 35 sacks cement @Identify the content 65 sacks cement, pulled up	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the depth place and to 3800' and 4 sacks cemes and to 3800'. Shot pipe @13 p to 300' and circulated 63 s	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumper acks cement to surface. Pulled rest		
Formation Content Describe in detail the manner placed and the method or method of bottom with second of sacks cement (1) of pipe and topped off with additional described.	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the depth place and to 3800' and 4 sacks cement to 300' and circulated 63 section is necessary, use 800 cription is necessary, use 800.	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet oach set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumper acks cement to surface. Pulled rest to feet to surface.		
Formation Content Describe in detail the manner placed and the method or method of bottom with second of sacks cement (1) of pipe and topped off with additional described.	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the depth place and to 3800' and 4 sacks cement to 300' and circulated 63 section is necessary, use 800 cription is necessary, use 800.	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet oach set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumper acks cement to surface. Pulled rest to feet to surface.		
Formation Content Describe in detail the manner placed and the method or method of bottom with sepumped 35 sacks cement @If additional describe in detail the manner placed and the method or method of bottom with sepumped 35 sacks cement @If additional described in the content of the con	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and seed in introducing it in the following and the seed of same and depth places and to 3800' and 4 sacks cement of same and circulated 63 seed to 300' and	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumper acks cement to surface. Pulled rest		
Formation Content Describe in detail the manner placed and the method or method are used, state the charace Plugged off bottom with so pumped 35 sacks cement @I 65 sacks cement, pulled up of pipe and topped off with additional described in the same of Plugging Contractor. Address P.O. Box 347 Character.	From To Size From To Size 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the deriver of same and depth place and to 3800' and 4 sacks cement of same and circulated 63 section is necessary, use BAC KELSO CASING PULLING, Indexe, Kansas 67524	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluged, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumper acks cement to surface. Pulled rest 1, 10% gel. Plugging Complete. CK of this form.) NC. License No. 6050		
Formation Content Describe in detail the manner placed and the method or method of pumped 35 sacks cement @10 65 sacks cement, pulled upof pipe and topped off with additional described in the pumped 35 sacks cement. Name of Plugging Contractor Address P.O. Box 347 Chamber of Party Responsible For	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the form of same and depth place and to 3800' and 4 sacks cemes 600' to 2200'. Shot pipe @13 po to 300' and circulated 63 seription is necessary, use BAC KELSO CASING PULLING, I hase, Kansas 67524 PLUGGING FEES: Petroleum	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluge and, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumpe acks cement to surface. Pulled rest 1, 10% gel. Plugging Complete. CK of this form.) NC. License No. 6050		
Formation Content Describe in detail the manner placed and the method or method of bottom with sepumped 35 sacks cement @Io 65 sacks cement, pulled up of pipe and topped off with additional described in the pumped 35 sacks cement. Name of Plugging Contractor Address P.O. Box 347 Chamber of Party Responsible For	From To Sizo From To Sizo 8-5/8" 4-1/2" In which the well was plugged and sused in introducing it in the ter of same and depth place and to 3800' and 4 sacks cemes to 3800' and circulated 63 secription is necessary, use BAC KELSO CASING PULLING, I hase, Kansas 67524 PLUGGING FEES: Petroleum COUNTY OF Rice	Put in Pulled out 244' none 4037' 1121' I, Indicating where the mud fluid want to the hole. If coment or other pluge and, from feet to feet each set nt. Shot pipe @2200', 1800', 1600', 30', 1121', pulled up to 975', pumpe acks cement to surface. Pulled rest 1, 10% gel. Plugging Complete. CK of this form.) NC. License No. 6050		

OIL, GAS OR W	ATER RECORDS			C	ASING RECO	ORD .		
			CASING RECORD					
ormation						In the fourt		
	Content	From	То	Sizo	Put In	Pulled out		
and the second s			\ 	8-5/8"	244	none		
			·	4-1/2"	4037'	1121'		
				-				
· · · · · · · · · · · · · · · · · · ·				-				
		- ublab tho w		as plugge	d. Indica	ting where the mud fluid woole. If coment or other pl		
scribe in de	tall the manner i	d will include	teads	icina it i	nto the he	teet to feet each se		
laced and the	e method or metho	as usou iii iii	5 d d	onth nlac	ed. from	feet to feet each se		
are used. St	ate the characte	er of Same a	/	andre come	nt Shot	Tripe @22001, 18001, 1600		
Pluggea or	E DOCCOIII WICH San	21 (22001	Cha	E mino al	ולוד יחני	', pulled up to 9/5', pum		
pumped 35	sacks cement @160	0. 60 2200 •	5110	12+04 63 6	acks ceme	r, pulled up to 975', pument to surface. Pulled replaying Complete.		
65 sacks c	ement, pulled up	to 300' and o	<u>STECU</u>	CE /25 mag	109 001	Plugging Complete.		
(11	d topped off With additional descr	iption is nec	ossar	y, usu <u>on</u>	<u> </u>			
ame of Plugg!	ng Contractor	<u>KELSO CASIN</u>	<u>GPU</u>	J. L. ING.	111.	License No. 6050		
					•			
idress P.	O. Box 347 Cha	se, Kansas	673	2.1				
400 (1)	RESPONSIBLE FOR P			Detroleur	n Property	y Services, Inc.		
AME OF PARTY	RESPONSIBLE FOR P	LUGGING FEES:	<u> </u>	recrosed	W TIOPULS.			
	•	2011/27/ 05		Rice		. S.S.		
TATE OF	Kansas	COUNTY OF		KICC				
		volen			Employee	of Operator) or (Operator)		
·, , .					. That I	have knowledge of the tac		
bove-describe	d well, being fir	st duly sworn	nd th	ne Lou of	the above	-described well as filed t		
tatements, a	ind matters nerei	co bolo me Go	d.	, , , , ,	49			
he same are t	rue and correct,	50 Herb 1110 00		(Slanature)	and Har		
	•					, –		
•				(Address)	P.O. B	ox 347 Chase, KS. 67524		
•				(11001 000)		OF CHUIC		
		CHOON TO bad	oro i	no this	15th _{day}	of June		
	SUBSCRIBED AND	SMOKN TO DE	010	"° '''''	,	STATELIN		
					sme)	Lessberg 7 19		
•			-		No	tary Public JUN 17		
				~_	110	tary Pubalc		
•	My Commission	Expiros:		IRENE HER State of K My Appl. Exp. As	ansas	CONSERVATION DI		