Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-5 August 2008 Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Resource Operations, Inc.	License Number: 30364
Operator Address: P O Box 9487, Tulsa OK 74157-0487	
Contact Person: Mike Harmon	Phone Number: (918) 446 - 6114
Permit Number (API No. if applicable): 15-009- 20 857000	Lease Name: Dewerff
Source of Waste:	Well Number: #4 SWD
Emergency Pit Settling Pit Workover Pit Drilling Pit Burn Pit Haul-off Pit Steel Pit Spill / Escape Type of waste to be disposed:	Source Location (QQQQ): C - NE - NE - SE Sec. 2 Twp. 20 R. 12 East West 2310 Feet from North / South Line of Section 330 Feet from East / West Line of Section Barton County
Amount of waste: No. of loads 100 Barrels	TonsYDS
	se Road Dike / Berm Other:
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal:	Date of Waste Transfer: May 14, 2010
Operator Name: Resource Operations, Inc.	License No.: 30364
Lease Name: C Grove #3 SWD	Sec. <u>29 </u>
Docket No./API No.: D-04173	County: Rice
Comments:	RECEIVED MAY 2 9 2310 KCC WICHITA
The undersigned herby certifies that he / she is Production Superintendent for Resource Operations, Inc. (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his / her knowledge and belief. Subscribed and sworn to be fire the on this DETHEVABUZ Notary Public State of Oklahoma My Commission Expires 199011683 Expires 08/29/11	

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

EXPLORATION & PRODUCTION WASTE TRANSFER (FORM CDP-5)

Instructions

General Instruction.

1. Form must be typed.

Section 1: Operator Information.

- Operator Name. Enter the operator's full name as it appears on operator's license.
- 1b. License #. Enter the operator's license number. To verify KCC operator license information check the Commission's website at http://kcc.ks.gov/conservation/oil_license.cgi or contact the Conservation Division's Licensing Department at (316) 337-6194.
- Operator Address. Enter the operator's mailing address: street or PO box number, city, state, and zip code.
- 1d. Contact Person. Enter the name of the individual who will be the operator's contact person for this Exploration and Production Waste Transfer Form, should the Conservation Division Staff need to contact the operator about the form. The contact person may be the operator or the operator's agent.
- Phone. Enter the phone number of the contact person that the Conservation Division Staff may easily reach if necessary to discuss the form.

Section 2: Waste Source.

- 2a. Permit Number (API No. if applicable). Enter the KCC permit number for the pit where the waste to be disposed of or transferred originated. For workover, drilling, and haul-off pits, the Permit Number is the API Number. For emergency, settling, and burn pits, the Permit Number is listed at the bottom of the approved Application for Surface Pit (CDP-1) Form in the "KCC Office Use Only" Section.
- Source of Waste. Mark the appropriate box to indicate the waste origin.
- 2c. Lease Name. Enter the lease name where the waste originated.
- 2d. Well Number. Enter the well number where the waste originated.
- 2e. Waste Origin Geographic Location.
 - 2e(1). QQQQ. Enter the ¼ ¼ ¼ ¼ location within the section of the waste origin.
 - 2e(2). Sec., Twp., and R. Enter the section, township and range number where the waste origin is located and mark the appropriate box to indicate if the range is East or West of the Sixth Principal Meridian.
 - 2e(3). Footage from Section Lines. Enter the number of feet the waste origin is located from the North or South section line and mark the appropriate box to indicate from which section line the measurement was taken. Enter the number of feet the waste origin is located from the East or West section line and mark the appropriate box to indicate from which section line the measurement was taken.
 - 2e(4). County. Enter the county where the waste originated.

Section 3: Type and Amount of Waste.

- 3a. Type of Waste. Mark the appropriate box to indicate the type of waste to be transferred and disposed. If the type of waste is not fluid, soil, or drilling mud/cuttings, mark the "Other" box and give a simple but specific description of the type of waste.
- 3b. Amount of Waste. Enter the amount of waste to be transferred and disposed in the appropriate box, according to how the quantity of waste is measured.

Section 4: Waste Destination.

- 4a. Destination. Mark the appropriate box to indicate how the waste will be disposed. If the disposal method is not provided, mark the "Other" box and give a simple but specific description of the disposal method.
- 4b. Transfers to Reserve Pit. Mark the appropriate box to indicate if the waste is being transferred to a reserve pit on an active lease.
- 4c. Location of Waste Disposal.
 - Operator Name. Enter the disposing operator's full name as it appears on operator's license.
 - 4c(2). Lease Name. Enter the name of the lease where the subject waste will be disposed.
 - 4c(3). Docket No. Enter the KCC Docket Number under which the disposing operator is permitted for disposal on the disposing lease.
 - 4c(4). Date of Waste Transfer. Enter the date when the subject waste will be transferred.
 - 4c(5). License No. Enter the disposing operator's license number. To verify KCC operator license information check the Commission's website at http://kcc.ks.gov/conservation/oil_license.cg or contact the Conservation Division's Licensing Department at (316) 337-6194.
 - 4c(6). Sec., Twp., R. Enter the section, township and range number where the waste disposal is located and mark the appropriate box to indicate if the range is East or West of the Sixth Principal Meridian.
 - 4c(7). County. Enter the county where the waste disposal is located.
 - 4c(8). Comments. Enter any additional comments.

Section 5: Verification.

- Position with operator. Enter the position the person completing the Exploration & Production Waste Transfer Form holds with the operator.
- 5b. Operator Name. Enter the operator's full name as it appears in Section 1a
- Signature. The applicant must sign the Closure of Surface Pit Form in front of a legal notary to verify that the information on the form is true and correct.
- 5d. Legal Notary. A legal notary will complete the 5d sections.