

15-De3-00041-00-00

KANSAS  
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Gove

Location: SE SE SE Sec. 17 Twp. 12 Rge. 30 (E) (W)

Name of Field: \_\_\_\_\_ Total Depth: 4535

I have this date completed supervision of plugging of:

Lease Name: Kiaser Well No. 1

Operator's Full Name: Burch Drlg Co, Inc.

Complete Address: 1011 Union Center Wichita Kansas.

Plugging Contractor: Same

Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A \_\_\_\_\_

Other well as hereafter indicated: Dry Hole

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No X

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 11pm Day 31 Month Oct Year 1958

The above well was plugged as follows:

TD- 4335 8 5/8" set at 225' cwc

Run hole with heavy mud set cementing plug at 540' and displace 20 sax cement thru drill pipe, mud to 220' set cementing plug and 15 sax cement, mud to 40' set and tie cementing plug in place 1/2 sax hulls and 10 sax cement to bottom of cellar.

Signed: Gilbert O. Leiker  
Conservation Division Agent

Reviewed: J. Lewis Brock  
Field Supervisor

Remarks:

PLUGGING  
FILE SEC. 17 T. 12 R. 30W  
BOOK PAGE 145 LINE 4

RECEIVED  
STATE CORPORATION COMMISSION

NOV 12 1958  
11-12-1958  
CONSERVATION DIVISION  
Wichita, Kansas