Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Kinder Morgan Interstate Gas Transmission LLC	. 1
Operator Name: Kinder Morgan Interstate Gas Transmission LLC	License Number: #34002
Operator Address: 145 N. Country Club Drive - Colby, KS 67701	
Contact Person: Mark Bredemeier - Corrosion Technician	Phone Number: (785) 462 - 6815 ext. 223
Permit Number (API No. if applicable): #039-21113-00-00	Lease Name & Well No.: PXP #64
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SW NW NW NW
Settling Pit	Sec. 28 Twp. 04S R. 26 East West
☐ Workover Pit ☐ Haul-Off Pit	570 Feet from North / South Line of Section
	75 Feet from East / West Line of Section
	County
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Sides And Bottom Of Pit Was Sealed With Bentonite Slur	ry
Sides And Bottom Of Pit Was Sealed With Bentonite Slur	ry
Abandonment procedure of pit:	
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Wa	
Abandonment procedure of pit:	
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Wa	
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Water Dry Out And Then Covered. The undersigned hereby certifies that he / she is Corrosion Technician a duly authorized agent, that all information shown hereon is true and correct to the	nter Being Muddy. Mud Pit Was Allowed To n for Kinder Morgan Interstate Gas Transmission (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Water Dry Out And Then Covered. The undersigned hereby certifies that he / she is Corrosion Technician a duly authorized agent, that all information shown hereon is true and correct to the	nter Being Muddy. Mud Pit Was Allowed To n for Kinder Morgan Interstate Gas Transmission (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Water Dry Out And Then Covered. The undersigned hereby certifies that he / she is Corrosion Technician a duly authorized agent, that all information shown hereon is true and correct to the	nter Being Muddy. Mud Pit Was Allowed To
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Water Dry Out And Then Covered. The undersigned hereby certifies that he / she is Corrosion Technician a duly authorized agent, that all information shown hereon is true and correct to the	nfor Kinder Morgan Interstate Gas Transmission (Co.), be best of his /her knowledge and belief. Bullinger Signature of Applicant or Agent
Abandonment procedure of pit: Unable To Pump Fresh Water From Pit Due To Fresh Water Dry Out And Then Covered. The undersigned hereby certifies that he / she is Corrosion Technician a duly authorized agent, that all information shown hereon is true and correct to the	nfor Kinder Morgan Interstate Gas Transmission (Co.), be best of his /her knowledge and belief. Bullinger Signature of Applicant or Agent

January 13, 2013

My Commission Expires: \(\)

JUN 21 2010