Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

API No. 15 - 051-03496-0000 OPERATOR: License #: 34318 Name: Berexco, L.L.C. Address 1: P. O. Box 723 Sec. 1 Twp. 12 S.\R. 18 Address 2: P. O. Box 20380, Wichita, KS 67206 1,530 _ Feet from -City: Hays State: KS Zip: 67637 + ____ Feet from Contact Person: __Curtis Gabel_ Footages Calculated from Nearest Outside Section Corner: Phone: (785) 628-6101 Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: Lease Name: Karlin Well #: _A-4 Gas Storage Permit #: Date Well Completed: 8-27-51 Is ACO-1 filed? Yes No If not, is well log attached? Yes No The plugging proposal was approved on: ____ Producing Formation(s): List All (If needed attach another sheet) bv: Bruce Basye (KCC District Agent's Name) KCB Depth to Top: 3384' Bottom: 3388' Plugging Commenced: 5-26-10 ARB Depth to Top: 3631' Bottom: 3656' T.D. Plugging Completed: 5-27-10 12:00 P.M. ____ Depth to Top: ___ Bottom: ____ Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface, Conductor & Production) Formation Content Casing Size Setting Depth Pulled Out RECEIVED IUN 0/2 2010 8 5/8 128' 4 1/2 3681' Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Run tubing open end to 3600', rig up Allied. Mix 150 sks 60/40 Pos w/4% gel and 300# of hulls. Pull tubing to 1800', mix 75 sks cement w 300# hulls. Circulate to surface. Pull rest of tubing. Hook up to 8 5/8. Mix 25 sks, pump down 8 5/8 press to 300#, pump 10 sks down 4 1/2 and top off. Done plugging at 12:00 p.m. KCC rep Marvin Mills was present for plugging. Rig down and move off.

my