

15-167-03866-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Okmar Oil Company Address 817 Union National Bldg., Wichita
(Applicant)

Lease (Farm Name) Bowlby Well No. 1

Well Location SW $\frac{1}{4}$ SE $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. (9 Twp. 11S Rge. 15W (X) (W)

County Russell Field Name (if any) _____

Total Depth 3430' Oil _____ Gas _____ Dry Hole x

Was well log filed with application? yes If not, explain: _____

Date and hour plugging is desired to begin 11-6-57 @ 9:00 p.m.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner Mr. P. H. Jackson

P. O. Box 368 Address Great Bend, Kansas

Plugging Contractor Leben Drilling, Inc.

Plugging Contractor's License No. -

Address 905 Central Bldg., Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Okmar Oil Company Address same as above

and payment will be guaranteed by applicant.

James M. Batten
Applicant or Acting Agent

Date November 7, 1957

RECEIVED
STATE CORPORATION COMMISSION
11-20-57
NOV 20 1957
CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC. 9 T. 11 R. 15W
BOOK PAGE 61 LINE 6

15-167-03866-0000

STATE OF KANSAS
State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas
November 13, 1957


Well No. 1
Lease Donby
Description SW SE SE 9-11-15W
County Russell
File No. 61-6

Owner Oil Company
617 Union National Building
Wichita, Kansas

Content:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Donald Trunn, Rt. 1, Russell, Kansas Phone 2016 Corham, Kans.

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor