STATE OF KANSAS STATE CORPORATION (200°Colorado Derby Wichita, Kansas 6	COMMISSION Building	K.A.R.			LEASE NA	BER 15-167	- 36517-000; F.H. Booth
*	and	E: FIII	out c	NT ompletely ons Div.	49 50		A-1 S Section Line
				,	2970	Ft. from	E Section Line
LEASE OPERATOR Quinoco Petroleum, Inc.					SEC. 32	TWP.115 RG	E.15 (X)or(V)
ADDRESS P.O. Box 378111, Denver, CO 80237					COUNTY _	Ru	ssell
PHONE # (303) 850-7373 OPERATORS LICENSE NO. 03613					Date Wel	1 Complete	d 4-25
Character of Well Oil					Plugging	Commenced	6-9-88
(OII, Gas, D&A, SWI	•	pply Wei	1)		Plugging	Completed	6-10-88
Did you notify the							
Which KCC Office d	ld you notify? H	ays Dist	rict (Office - I	KCC Rep. De	nnis Hamel	
Is ACO-1 filed?	Yes If not,	is well	log a	ttached?			
Producing Formation						^m 3186 ^T	· ^D · <u>3186</u>
Show depth and thic		**IrKC	A&I indga				*2605-15 ′ **2880-3914 ′
OIL, GAS OR WATER	RECORDS	<u> </u>		. C.	ASING RECOR	D	
Formation Topeka	Content Oil	From Surf	To 2589	S1 ze 8-1/4	Put In	Pulled out No	
Toronto L-KC "A"	Oil	Surf	2000	6-5/8	X	No	
IKC *B**	Oil_	Surf	2000	0 3/0			
Please see new	thod or methods us the character of	ed in in	troduc	ing It I	nto the hol	e. If cemer	nt or other plug
(If add)	itional descriptio	n Is nec	essary	, use BA	CK of this	form.)	
Name of Plugging Co For :	ontractor Kelso (347, Chase, Kansas	Casing Post 67524	ullers		L	icense No	6050
STATE OF Color	radio co	UNTY OF	Denve	r		,55•	
Janet Wilkerson	n	•		(Fm	nlovee of O	nerator) o	r (Operator) o
above-described we statements, and mat the same are true a	tters herein conta	ined and	the 1	oath, says	s: That I h e above-des	ave knowled	dge of the facts I as filed tha
			(/	(ddress	P.O. Box	378111, Der	wer, co
Start St	UBSCRIBED AND SWOR	N TO bef	ore me	this	8th day o	f July	,19 88
The state of the s			~ <i>[</i>		AE COMPORATE NO Ta	TY Public	urdy
↑ the My	Commission Expir	es:	<u>4/ə</u>	1/88	Reur		lia A. Purdy

JUL 1 4 1988 07-14-88

Form CP-4 Revised 07-86 Pumped 50 sx common cmt down tbg to 2800'. Shot tbg @ 2700', could not pull, shot @ 2000', could not pull, stuck @ 1520'. Pump 100 sx cmt down tbg, displace to \pm 800'. P.O. shot tbg @ 800'. RU Howco to 2-7/8" tbg, pump 3 sx hulls, 100 sx 60-40 poz mix with 1/4# flowseal/sx. RU & shot tbg @ 800', pull tbg. RU Howco to 6-5/8" csg, pump 5 sx hulls and 200 sx cmt. Hook up to 10-3/4" surf pipe. Press to 700#, held OK. Close well in.