STATE CORPORATION CO Wichita State Office Bldg I 130 S. Market, Room 2078	OMMISSION	NE NW	NE	•		
•				Sec/Twp/Rge	Sec 16 T2	9S R17E
130 S Market Room 2078	PLUGGING SECTION	5170 (	GPS)	feet from so	uth section	line
Wichita, Kansas 67202	, ·	<u>1631 (</u>	GPS)	feet from ea	st section lin	ne
TECHNICIAN'S PLUGGING	REPORT	Lease/W	Vell#	Stich North-	Wiles gps#	MCD 12
Operator License # 101		County		Wilson	·	
Operator: State Of Kansas	Fee Fund	Well Tot	al Depth	850 (est)		feet
Name & Stich North Proje	ect	Producti	on Pipe:	NA	_Size Feet	NA
Address		Surface	Casing:	10	_Size Feet	NA
AB oil well XXXXXX Gas	s Well	SWD Well/ Inp	ut Well		D&A	
Other well as hereinafter ind	licated:				- 11 -	
Plugging Contractor: K-W	Oil Well Service, Inc	·		·	_ Lic. #	3097
Address: 19450 Ford Road	d, Chanute, Kansas 66	720		<del> </del>		
Company to plug at:	Hour: [	Day:	2	Month:	7	2009
Plugging proposal received	from: Sam Kepley	į				
Company Name: K-W	Oil Well Service, Inc	1		Phone:	620-433-7	730
	and fill from btm to top	with portland c	ement.			
				Alan M. Dun	nina	
Were: Wash well to TD	Plugging Proposa			Alan M. Dun	TECHNICIAN	
Were: Wash well to TD  Plugging attended by Agent:	Plugging Proposa	al Received by	: Part	xxxxx	TECHNICIAN None	
Were: Wash well to TD  Plugging attended by Agent: Operations Completed: Hou	Plugging Proposa	al Received by Day:	: Part 2	XXXXXX Month:	TECHNICIAN None 7	2009
Were: Wash well to TD  Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report:	Plugging Proposa All ur: 3' of 12" surface p	al Received by Day: pipe was set to	: Part 2 bring we	XXXXXX  Month:	TECHNICIAN None 7 A 1" ceme	2009 nt string
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we	Plugging Propose All ur: 3' of 12" surface pell was then pumped full	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin	2009 nt string g. A
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland	Plugging Propose All ur: 3' of 12" surface pell was then pumped full	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin	2009 nt string g. A
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we	Plugging Propose All ur: 3' of 12" surface pell was then pumped full	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin	2009 nt string g. A
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland	Plugging Propose All ur: 3' of 12" surface pell was then pumped full	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement string plow depth	2009 nt string g. A
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland the location restored.	Plugging Proposa  All  ar:  3' of 12" surface pell was then pumped full dicement were used to performed to pe	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin plow depth	2009 nt string g. A and
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland the location restored.  Remarks: Control # 200900	Plugging Proposa  All  ar:  3' of 12" surface pell was then pumped full dicement were used to performed to pe	al Received by  Day:  pipe was set to of cement from olug well. The	: Part 2 b bring we m btm to	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin plow depth	2009 nt string g. A and  RECEIVED CORPORATION CO
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland the location restored.  Remarks: Control # 200900 (If addi	Plugging Proposa All  ar:  3' of 12" surface pell was then pumped full dicement were used to pell cement were used to pel	al Received by  Day:  pipe was set to of cement from olug well. The	: Part 2 b bring we m btm to	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin plow depth	2009 nt string g. A and RECEIVED CORPORATION CO
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland the location restored.  Remarks: Control # 200900 (If addi	Plugging Proposa All ur: 3' of 12" surface pell was then pumped full dicement were used to perform the pumped for performance of the pumped full dicement were used to perform the pumped for performance of the performance o	al Received by  Day:  pipe was set to of cement from olug well. The	: Part 2 b bring we m btm to	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin plow depth	2009 nt string g. A and  RECEIVED CORPORATION CO
Plugging attended by Agent: Operations Completed: Hou Actual Plugging Report: was washed to 500' The we total of 156 sacks of portland the location restored.	Plugging Proposa  All  ar:  3' of 12" surface pell was then pumped full dicement were used to performed to pe	al Received by Day: pipe was set to of cement fron	Part 2 bring we	XXXXXX  Month: ell to surface. top thru this o	TECHNICIAN None 7 A 1" ceme cement strin plow depth	200 nt string g. A and RECEIV