To:	API NUMBER 1	15-205- 19900-00-00
STATE CORPORATION COMMISSION	SE SE NW S	Sec/Twp/Rge <u>14-27-15E</u>
Wichita State Office Bldg PLUGGING SECTION	2783 (GPS) for	eet from south section line
130 S. Market, Room 2078 Wichita, Kansas 67202	2695 (GPS) fo	eet from east section line
TECHNICIAN'S PLUGGING REPORT	Lease/Well# <u>N</u>	Milligan II #MIL 03 (GPS)
Operator License # 101	County <u>V</u>	<i>N</i> ilson
Operator: State Of Kansas Fee Fund	Well Total Depth 8	350 (est) feet
Name & Milligan II Project	Production Pipe: N	NA Size Feet NA
Address	Surface Casing: N	NASize Feet NA
AB oil well XXXXXX Gas Well SW	D Well/ Input Well _	D&A
Other well as hereinafter indicated:		
Plugging Contractor: Kepley Well Service, LLC		Lic. #33749
Address: 19245 Ford Road, Chanute, Kansas 66720		
Company to plug at: Hour: Day	<i>y</i> :3	Month: <u>5</u> 2010
Plugging proposal received from: <u>Jeff Friederich</u>		
Company Name:	F	Phone:
Were: Clean well to TD and then pump full of cem	ent thru cement string	J
Plugging Proposal F	Received by:	Alan M. Dunning TECHNICIAN
Plugging attended by Agent: All	Part _	None XXXXXX
Operations Completed: Hour: Day	<i>y</i> :3	Month: <u>5</u> 2010
Actual Plugging Report: A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of whether the All Plugging Reports A large portion of white All Plugging Reports A large portion of the All Plugging Reports A large portion	nat appears to be a wo	ooden bridge truss was removed
from open hole. The wood truss is approx 4' long and	rectangular (12" X 14"	'). Surface pipe was set and
the well washed to 560' thru a 1" cement string but co	uld go no deeper. The	e well was then pumped full of
cement from btm to top thru this cement string. A total	of 212 sacks of portla	and cement were used to plug
well. The well was cut off below plow depth and the lo	ocation restored.	
		RECEIVED KANSAS CORPORATION COM
		MAY 2 8 2010
Remarks: Control #20100039-001		
(If additional description is necessary, u	se <u>BACK</u> of this form.)	CONSERVATION DIVIS WICHITA, KS
I did not observe this plugging.		7
	Signed:	Sommel I of mold
		TECHNICIAN