

Kansas Corporation Commission 1037264 Oil & Gas Conservation Division

Form CDP-1 April 2004 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate

Operator Name: Hess Oil Company			License Number: 5663
Operator Address: PO BOX 1009			MCPHERSON KS 67460
Contact Person: Bryan Hess			Phone Number: 620-241-4640
Lease Name & Well No.: Kriley B-4		1	Pit Location (QQQQ):
Type of Pit:	Pit is:		<u>SE_NW_SW</u>
Emergency Pit			
If the pit is lined give a brief description of the liner material, thickness and installation procedure. Describe procedures for periodic maintenance and determining liner integrity, including any special monitoring. NA			
Distance to nearest water well within one-mile of pit 1149 feet Depth of water well 45 feet		Depth to shallowest fresh water	
Emergency, Settling and Burn Pits ONLY:		Drilling, Workover and Haul-Off Pits ONLY:	
Producing Formation:		Type of material utilized in drilling/workover: water	
Number of producing wells on lease:		Number of working pits to be utilized:1	
Barrels of fluid produced daily: Does the slope from the tank battery allow all spilled fluids to flow into the pit? Yes No		Abandonment procedure: Empty and backfill Drill pits must be closed within 365 days of spud date.	
Submitted Electronically			
KCC OFFICE USE ONLY Steel Pit RFAC RFAS			
Date Received:			



Mark Parkinson, Governor Thomas E. Wright, Chairman Joseph F. Harkins, Commissioner

April 21, 2010

Bryan Hess Hess Oil Company PO BOX 1009 MCPHERSON, KS 67460-1009

Re: Drilling Pit Application Kriley B-4 Sec.20-07S-17W Rooks County, Kansas

Dear Bryan Hess:

District staff has inspected the location and has determined that an unsealed condition will present a pollution threat to water resources.

District staff has recommended that the Workover pit be lined. If a plastic liner is to be used it must have a minimum thickness of 10 mil. Integrity of the liner must be maintained at all times.

NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The free fluids in the Workover pit should be removed as soon as practical after drilling operations have ceased. The fluids should be taken to an authorized disposal well. Please call the District Office at (785) 625-0550 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through SOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (785) 625-0550.