

Mark Parkinson, Governor Thomas E. Wright, Chairman Joseph F. Harkins, Commissioner Ward Loyd, Commissioner

September 15, 2010

OXY USA, Inc. 1701 N. Kansas PO Box 2528 Liberal, KS 67905

Re:

Dwyer 5-F32-32-39

SENW Sec. 32-32S-39W Morton County, Kansas API # 15-129-21866-00-00

Dear Sir or Madam:

This letter is to inform you that you have been granted an additional extension of time in which to close the drilling pits associated with the drilling of the Dwyer #5-F32-32-39 well.

The original 365 days for closure expired on 09/15/2010. This extension will expire 11/15/2010. We urge you to make every effort to close these pits within this time frame. In the event there is water standing in these pits, please dewater and dispose of fluids in an authorized disposal facility to expedite closure. Extension of this time frame automatically extends the time period for filing the closure of surface pit form.

Failure to close the pit or request an additional extension prior to the expiration date may result in a fine in accordance with K.A.R. 82-3-602(a). An additional extension will only be granted for good cause and after K.C.C. field staff has made an inspection of the site. Should field staff discover that said pit has been closed before the date of extension request, an administrative penalty may be assessed to you through K.C.C. invoice.

If you have any questions in this regard, please do not hesitate to contact Kathy Haynes at (316) 337-6243.

Very sincerely yours,

Doug Louis
Director

Cc:

File

District

prod m' 10



OXY USA Inc.

1701 N. Kansas P.O. Box 2528 Liberal, Kansas 67905

September 2, 2010

Kansas Corporation Commission Oil & Gas Conservation Division 130 South Market Room 2078 Wichita, KS 67202

RE:

OXY USA, Inc.

Dwyer 5-F32-32-39

API 15-129-21866-00-00 SW NW SE NW 32-32S-39W

Morton County, KS

Dear Kathy Haynes:

I am writing to request an extension of time to close the drilling pit associated with the drilling of the subject well. Presco Western, LLC, Operator License #32309, formerly operated this well. It is now operated by Oxy USA, Inc., Operator License #5447.

The original 365 days for closure expires on September 15, 2010. We are requesting a six month extension of time for closure.

If there are any questions or you require further information, contact me at the above address or by phone at (620) 629-4253.

Sincerely,

Laura Beth Hickert

Cc: OXY- Houston

Well Files

RECEIVED
SEP 0 3 2010
KCC WICHITA

FILTER SEL ompany	Fin	Search Well In API Number	<u>ventory</u>	Sec	Twp R	ngn	7	14
PI # 15-129-21866-	00-00 W	II DWYER 5-F32	-32-39		Cty MC	RTON	Dkt	
Oper 32309	PRESCO W	ESTERN LLC	A	Lgcy Oper				
Vork Oper				C-1 Oper	PRESCO	WESTER	VLLC .	
L Type DH	WL Stat	PA Status S	ource: CP23	Status D	: 09/27/	2009		
cation 32-328-39	W SWNWSE	NW, 1787 FNL 1582	FWL	enter et innermationen in innermation		<u></u>	Distr	ict # 01
<u>Dates</u>						la l		
Intent Apprv:	02/27/2009	Comp	ol: 09/27/2009					
Permit Expire:	02/27/2010	Compl Rpt Re	c: 11/09/2009					
ACO-1 Spud:		Plugge	d: 09/27/2009				ing Marie	
District Spud:	09/15/2009							
	, a						etronomic de la constanta	
<u>Drilling</u>			Spud Ltr:	CP 1:		initamiantany.		
SC Int:	580		SGWA: ✓	CP 1:	Date C	P-2/3 Rec'd:	10/02/20	***************************************
PIT Cls EXT	300		RFAC 🗹	CP 4: ✓	Date C	P-4 Rec'd:	11/09/200	9
Pit Cls:			RFA 🗌	CDP 5: Y				
PIT Status:			PitLiner [
444	HD	BBLS 540	Steel 🗌		e de la composición dela composición de la composición dela composición de la compos			a religio d'Assas
					PROTECT AND			
							era o S	