

To: STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING SECTION
200 COLORADO DERBY BUILDING
WICHITA, KANSAS 67202

API NUMBER 15-051-23, 226-00-00

SE, Sec. 12, T 13S, R 17 W/E

990 feet from 10 section line

990 feet from 10E section line

TECHNICIAN'S PLUGGING REPORT

Operator License # 5541

Lease Name HUMAN Well # 2

Operator: WEILERT ENTERPRISES
Name &

County ELLIS

Address Box 652
1011 E-Hwy 40 BY PASS
HAYS, KANSAS. 67601

Well Total Depth 2620 feet

Conductor Pipe: Size 0 feet

Surface Casing: Size 8 5/8 feet 201

Abandoned Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D&A X

Other well as hereinafter indicated _____

Plugging Contractor HELBERG DRILL License Number 267

Address Box 32 MORLEY D HAYS. 67650

Company to plug at: Hour: 3:00 PM Day: 18 Month: NOV. Year: 1982

VERBAL PLUGGING ORDERS GIVEN TO BUSTER WEILERT

(company name) WEILERT ENTERPRISES, INC. (phone) 913-628-2324

were: 8 5/8" - 201 FT SR. OUL #125 ST COMMON-2% GEL-3% CA-CL. (544)

ORDER 180 ST 50% PZMIX 4% GEL-3% CA-CL. AND 8 5/8" PLUG.

SPOT WITH DRILL STEM - WITH HEAVY MUD BETWEEN ALL PLUGS.

1st PLUG @ 3540 FT #120 ST OUL - 2nd PLUG @ 1170 FT #120 ST OUL.

3rd PLUG @ 660 FT #180 ST OUL. - 4th PLUG @ 240 FT #140 ST OUL.

5th PLUG SOLID BRIDGE HULLS - PLUG @ 40' #10 ST OUL. Signed M. J. [Signature]

10 ST IN RATA HOLE (CIRCULATE) (TECHNICIAN) (DOIC)

Plugging Operations attended by Agent?: All _____ Part _____ None X

Operations Completed: Hour: 11:00 PM Day: 18 Month: NOV. Year: 1982

ACTUAL PLUGGING REPORT ORDERED 180 ST 50% PZMIX 4% GEL-3% CA-CL. + 8 5/8" PLUG

SPOTTED WITH DRILL STEM - WITH HEAVY MUD BETWEEN ALL PLUGS.

1st PLUG @ 3540 FT #120 ST OUL. - 2nd PLUG @ 1170 FT #120 ST OUL.

3rd PLUG @ 660 FT #180 ST OUL. - 4th PLUG @ 240 FT #140 ST OUL.

5th PLUG SOLID BRIDGE HULLS - PLUG @ 40' #10 ST OUL.

10 ST IN RATA HOLE (CIRCULATE) (CEMENTED BY SUN OUL.)

Remarks: _____

RECEIVED
STATE CORPORATION COMMISSION
DEC 6 1982
12-06-1982
CONSERVATION DIVISION
Wichita, Kansas

I hereby certify that the above plugging instructions were given as herein stated and that I (did / did not) observe this plugging.

Signed M. J. [Signature] (TECHNICIAN) (DOIC)
12-27-82
2090-W