KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:

Remarks:

RECEIVED STATE CORPORATION COMMISSION

MAR 1 2 1959

Jove Harket White 2 Kaneas File No. 14-32	Jewel M. Og	den, Director	•	•		· · · · · · · · · · · · · · · · · · ·	4K 12 19	J59 ·
Location: SE NW SW Sec. 25 Tep. 11 Rge. 17 (E) (W) Name of Field: Total Depth: 3384 I have this date completed supervision of plugging of: Lease Name: Rumsey Well No. 2 Operator's Full Name: E. H. Riggs Complete Address: Gll Union Natl Bldg Wichita, Kans Plugging Contractor: Forbes Casing Pulling Co Address: Great Bend, Kans License No. 49 Oil Well X Gas Well Input Well SWD Well D & A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes_No If yes how long? Reason: Operation Completed: Hour 3PM Day 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', hea mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	500 Insurance 212 North Ma	ce Building arket		٠.,		CON " PI	/A F.	
Name of Field: I have this date completed supervision of plugging of: Lease Name: Rumsey Querator's Full Name: E. H. Riggs Complete Address: Gll Union Natl Bldg Wichita, Kans Plugging Contractor: Forbes Gasing Pulling Co Address: Great Bend, Kans License No. 49 Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes_No. If yes how long? Reason: Operation Completed: Hour 3FM pay 9 Month 3 Year_ The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', heamud to 50', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.			County:_	Ellis		, 		
Name of Field: I have this date completed supervision of plugging of: Lease Name: Rumsey Querator's Full Name: E. H. Riggs Complete Address: Gll Union Natl Bldg Wichita, Kans Plugging Contractor: Forbes Gasing Pulling Co Address: Great Bend, Kans License No. 49 Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes_No. If yes how long? Reason: Operation Completed: Hour 3FM pay 9 Month 3 Year_ The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', heamud to 50', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	Location:	SE NW SW		Sec. 23	Twp	Rge. <u>17</u>	(E)	_(W)
Lease Name: Rumsey Well No. 2 Operator's Full Name: E. H. Riggs Complete Address: 611 Union Nat1 Bldg Wichita, Kans Plugging Contractor: Forbes Casing Pulling Co Address: Great Bend, Kans License No. 49 Oil Well X Gas Well Input Well SWD Well D&A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes No. If yes how long? Reason: Operation Completed: Hour 3PM Day 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', heavy mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	,				Total Depth:	3384	,	
Operator's Fuil Name: E. H. Riggs Complete Address: 611 Union Natl Bldg Wichita, Kans Plugging Contractor: Forbes Gasing Pulling Co Address: Great Bend, Kans License No. 49 Oil Well SwD Well D&A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? YesNo. If yes how long? Reason: Operation Completed: Hour 3FM bay 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heavy mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	I have this	date complete	d supervision of	plugging o	f:			
Operator's Full Name: E. H. Riggs Complete Address: 611 Union Natl Bldg Wichita, Kans Plugging Contractor: Forbes Casing Pulling Co Address: Great Bend, Kans License No. 49 Oil Weil X Gas Well Input Well SWD Well D&A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? Yes No. If yes how long? Reason: Operation Completed: Hour 3PM pay 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 5/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heave mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	Lease Name:	Run	nsey		Well	No. 2	· · · · · · · · · · · · · · · · · · ·	
Complete Address: 611 Union Nat1 Bldg Wichita, Kans Plugging Contractor: Forbes Gasing Pulling Co Address: Great Bend, Kans License No. 49 011 Well X Gas Well Input Well SWD Well D&A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? YesNo If yes how long? Reason: Operation Completed: Hour 3PM Day 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 5/4" 1097' circulated with cement 7" 3374' with 100 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', hea mud to 50', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.			E. H. Riggs			<u> </u>		
Plugging Contractor: Great Bend, Kans License No. 49 Oil Well X Gas Well Input Well SWD Well D&A Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? YesNo. If yes how long? Reason: Operation Completed: Hour 3PM Day 9 Month 3 Year_ The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 5374! With 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', heavy mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.				tl Bldg	Wichita, K	an s	· · · · · · · · · · · · · · · · · · ·	
Address: Great Bend, Kans License No. 49 Oil Well X Gas Well Input Well SWD Well D&A Other well as hereafter indicated; Was any delay in plugging operations caused by Conservation Division Agent? Yes No. If yes how long? Reason: Operation Completed: Hour 3PM Day 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 0374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 180', heamud to 50', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	Plugging Co	ntractor:	Forbes Casin	g Pulling	Co			
Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? YesNo_ If yes how long?	Address:		Great Bend,	Kans	Lice	nse No	49	
Other well as hereafter indicated: Was any delay in plugging operations caused by Conservation Division Agent? YesNo_ If yes how long?								
Was any delay in plugging operations caused by Conservation Division Agent? YesNo_ If yes how long?					•			
Operation Completed: Hour 3PM Day 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374' with 150 sax cement behind. Reda pump lost in hole, pulled 2077' of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heave mud to 30', set bridge and 10 sax cement to bottom cellar. Midding and cementing by Forbes Casing Pulling pump truck.	,				•		Yes	_No
Operation Completed: Hour 3PM bay 9 Month 3 Year The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374! with 150 sax cement behind. Reda pump lost in hole, pulled 2077! of 7" on 3-18-57 to recover pump. On 3-8-59 run 525! 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heave mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	•	,						
The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 5374! with 150 sax cement behind. Reda pump lost in hole, pulled 2077! of 7" on 3-18-57 to recover pump. On 3-8-59 run 525! 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525! - heavy mud to 180!, displaced 25 sax cement through 2" at 180!, heavy mud to 30!, set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	•					`		
The above well was plugged as follows: 15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 5374! with 150 sax cement behind. Reda pump lost in hole, pulled 2077! of 7" on 3-18-57 to recover pump. On 3-8-59 run 525! 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525! - heavy mud to 180!, displaced 25 sax cement through 2" at 180!, heavy mud to 30!, set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.		·						
15" at 75' circulated with cement - 10 3/4" 1097' circulated with cement 7" 3374! with 150 sax cement behind. Reda pump lost in hole, pulled 2077! of 7" on 3-18-57 to recover pump. On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heave mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	Operation C	completed: Hou	ır <u>3PM</u> ı)ay	Month	3	Ye.	ar59
Reda pump lost in hole, pulled 2077! of 7" on 3-18-57 to recover pump. On 3-8-59 run 525! 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525! - heavy mud to 180!, displaced 25 sax cement through 2" at 180!, heavy mud to 30!, set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.				- 10 3/4 ^{††}	1097' circu	lated wi	th cem	ent,
On 3-8-59 run 525' 2" tubing in hole and circulated hole with heavy mud through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heavy mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	7" 33741	with 150 sax	cement behin	d.				
through 2" tubing (35 sax Gel), displaced 25 sax cement through 2" at 525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heavy mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck.	Reda pump	lost in ho	le, pulled 207	71 of 7" (on 3-18-57 t	o recove	r pump	•
525' - heavy mud to 180', displaced 25 sax cement through 2" at 180', heamud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck. Signed:	On 3-8-59	run 525 2	tubing in ho	le and ci:	rculated hol	e with he	eavy m	ud
mud to 30', set bridge and 10 sax cement to bottom cellar. Mudding and cementing by Forbes Casing Pulling pump truck. Signed:	through 2	" tubing (3	35 sax Gel), d	isplaced	25 sax cemen	t through	h 2" a	t
Mudding and cementing by Forbes Casing Pulling pump truck. Signed:	525! - he	avy mud to	180', displace	d 25 sax	cement throu	gh 2" at	1801,	hea v y
Signed: Solon Fetty	mud to 30	, set bridg	ge and 10 sax	cement to	bottom cell	ar.		
Signed: Sdon Tett. Conservation Division Agent	Mudding a	nd cementing	g by Forbes Ca	sing Pull	ing pump tru	ck.		
Conservation Division Agent		1		Signed:	Ledon)	Tects.		
Reviewed: Lewis Brick PLUGGING Field Supervisor	(Reviewed:	Jews	Brock	Dagneu.		<i>P</i>	ion Age	nt

FILE SEC 23 T 11 R 17W BOOK PAGE 14 LINE 32