206

STATE CORPORATION COMMISSION PLUGGING SECTION NE NE Ny SEC. 6	To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION,		API NUMBER 15- 001-21,042-000-00			
100 C L 100 PM			NE NE NW SEC.	6,7	13s, R 20	w ak w
Secretarion 10 10 10 10 10 10 10 1	200 COLORA	DO DERBY BUILDING	4950	feet from	S section i	ine
Operator License			2970	 feet from	e E section 1	lne
Departor: Beren Corp		•				
Named Address Box 723	-	•				
Hays, Ks. 67601 Conductor Pipe: Size feet	Operator: Name&	Defen oofp				
Surface Casing: Size 8 5/8 test 285 Abandoned Oil Weilxx	Address		Well Total Dept	h <u>3843</u>	f	ee †
Abandoned Oil Well_xx Gas Wellinput WellSWD WellD&A Other well as hereinafter Indicated		Hays, Ks. 67601 · 913-628-6101				
Other veil as hereinafter Indicated			Surface Casing:	Size85	^{5/8} feet2	85
Plugging Contractor B. J. Services License Number Address Company to plug at: Hour: PN Day: 5 Month: Peb. Year:19 91 Plugging proposal received from George Jorgenson (company name) (phone) were: Ordered 350 sks 65/35 poz 8% gel w/500 lbs. hulls. Well recored: 8 5/8 set at 285 w/125 sks. 5% set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent7: All xx Pert None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5% casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max pei 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Eil additional description is necessary, use BACK of this form.) I Idid / discorts observe this plugging. Signed Maxwirth Market Mar	Abandoned	Oll Well_xx Gas Well	Input Well	_ SWD Well_	D&A	
Plugging Contractor B. J. Services License Number Address Company to plug at: Hour: PN Day: 5 Month: Peb. Year:19 91 Plugging proposal received from George Jorgenson (company name) (phone) were: Ordered 350 sks 65/35 poz 8% gel w/500 lbs. hulls. Well recored: 8 5/8 set at 285 w/125 sks. 5% set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent7: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb. Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5% casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Eil additional description is necessary, use BACK of this form.) I (did / discort) observe this plugging. Signed Market Mulls.	Other well	l as hereinafter indicated				
Address Company to plug at: Hour:pNDay:5Month:FebYear:19 _91						
Company to plug at: Hour: PN Day: 5 Month: Feb. Year:19 91 Plugging proposal received from George Jorgenson (company name) (phone) were: Ordered 350 sks 65/35 poz 8% gel w/500 lbs. hulls. Well recored: 8 5/8 set at 285 w/125 sks. 5½ set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent?: All xx Pert None Operations Completed: Hour: 1:00PN Day: 5 Month: Feb. Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Ei Dedditional description is necessary, use BACK of this form.) I (did / dispath; observe this plugging.				•		
Plugging proposal received from			5 Month:	Feb.	Year: 19 91	
Company name) Were: Ordered 350 sks 65/35 poz 8% gel w/500 lbs. hulls. Well recored: 8 5/8 set at 285 w/125 sks. 5½ set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb. Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N O C Lib additional description is necessary, use BACK of this form.) I (did / did not) backside. Signed Maxwill Amelled Remarks: N O C Lib additional description is necessary, use BACK of this form.) Signed Maxwill Amelled					_ ''00''.''	
Well recored: 8 5/8 set at 285 w/125 sks. 5½ set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent7: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N O C E Dadditional description is necessary, use BACK of this form.) I (did / dia.matx observe this plugging.		•				
Well recored: 8 5/8 set at 285 w/125 sks. 5½ set at 3832 w/200 sks. Sq 965-1030 w/100 sks. 765 w/75 sks and 735-835 w/70 sks. Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Peb Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. bulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Elipadditional description is necessary, use BACK of this form.) I (did / dia math) observe this plugging. Signed Maxwell Maxw						
Plugging Proposal Received by Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb. Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Lil additional description is necessary, use BACK of this form.) I (did / diametry observe this plugging.	were:	Ordered 350 sks 65/35 poz 8% ge	el w/500 lbs. hull	S •		
Plugging Proposal Received by (TECHNICIAN) Plugging Operations attended by Agent?: All_xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Libedditional description is necessary, use BACK of this form.) I (did / did not)x observe this plugging. Signed Market Mar		Well recored: 8 5/8 set at 28	5 w/125 sks. 5⅓ se	t at 3832 w	1/200 sks	
Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb. Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs bulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C El Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 20878 Signed Maxwett Muller Signed Maxwett Muller	·	Sq 965-1030 w/100 sks. 765 w/75	5 sks and 735-835	w/70 sks.	7.A	·
Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C El Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 20878 Signed Maxwett Muller		•				<u>.</u>
Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C El Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 20878 Signed Maxwett Muller					3-3) G	1991
Plugging Operations attended by Agent?: All xx Part None Operations Completed: Hour: 1:00PM Day: 5 Month: Feb Year: 19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C El Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 20878 Signed Maxwett Muller		Plugging Propo	sal Received by			-1-
Operations Completed: Hour: 1:00PM Day: 5 Month: Feb. Year:19 91 ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. bulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: NVOICE Dadditional description is necessary, use BACK of this form.) I (did / did not)x observe this plugging. Signed Maxwirt Muller 20878.				(TE	CHNICIAN)	
ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Lip additional description is necessary, use BACK of this form.) I (did / did net) observe this plugging. E 20878 Signed Maxwell Market	Plugging	Operations attended by Agent?: Al	I_xx Part_		None	
ACTUAL PLUGGING REPORT Mercury Wireline perf at 1525. Tied onto 5½ casing. Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: N V O C Lip additional description is necessary, use BACK of this form.) I (did / did net) observe this plugging. Signed Maxweller Miller	Operation	s Completed: Hour: 1:00PM Day:	5 Month:	Feb	Year:19 91	
Pumped 250 sks 65/35 poz 8% gel w/500 lbs. hulls max psi 600. Shut in 400 psi. Tied onto backside. Pumped 100 sks 65/35 poz 8% gel w/200 max psi and 100 shut in psi. Remarks: NVO C E(!Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 2-25-21. Signed Maxweller Michael Market M						
Remarks: N V O C E(1) additional description is necessary, use BACK of this form.) I (did / did not), observe this plugging. E 2-25-91 30878 Signed Marking Marki						
Remarks: NVOICE(ID additional description is necessary, use BACK of this form.) I (did / did.not), observe this plugging. E 2-25-91 20878. Signed Marying Miller (IECHNICIAN)			•	1		
Remarks: NVOICE(ID) additional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 2-25-91 30878 . Signed Marking Miller TECHNICIAN			imped 100 sks 03/3.	o poz ow ge	:I W/ 200	
NVO CE (Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 2-25-91 Signed Market Miller TECHNICIAN	_ , ,,	man por and roo blue in port				
NVO CE (Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 2-25-91 Signed Market Miller TECHNICIAN				***************************************		
NVO CE (Dadditional description is necessary, use BACK of this form.) I (did / did not) observe this plugging. E 2-25-91 Signed Market Miller TECHNICIAN						
I (did / did not) observe this plugging. E 2-25-91 30878 Signed Marying Miller (TECHNICIAN)	Remarks:_					
E 2-25-91 (1/5 Signed Marying Miller)	NVOI	C E dadditional description is	necessary, use BAC	K of this	form.)	_
20878 (I.V.)	1 (414 /	did not) observe this plugging.				
Marvin Miller	21	0878 . 045	Signed Ma	TECHNICI	miller	

FORM CP - 2/3