KANSAS W STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

RECEIVED

STATE CORPORATION COMMISSION

MAR 6 1962

CONSERVATION DIVISION

Wichita, Kansas

TO:
J. P. Roberts
Assistant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

15.051.05448.00.00

File No.	County: Ellis
Location; SW SW SW	Sec. 6 Twp. 13 Rge. (E) (W) 20
Name of Field:	Total Depth: 3834
	supervision of plugging of:
Lease Name: Egger	Well No. 1
	Henderson Oil Co
•	335 Union Center Wichita, Kansas
Plugging Contractor	Knight Casing Pulling Co
Address:	Chase, Kansas License No. 436
Other well as hereafter ind	iicated;
Other well as hereafter ind Was any delay in plugging of YesNoX	operations caused by Conservation Division Agent?
Other well as hereafter ind Was any delay in plugging of YesNoX	dicated:
Other well as hereafter ind Was any delay in plugging of YesNoX	icated: operations caused by Conservation Division Agent?
Other well as hereafter ind Was any delay in plugging of Yes No X If Yes how long?	icated: operations caused by Conservation Division Agent?
Other well as hereafter ind Was any delay in plugging of Yes No X If Yes how long?	perations caused by Conservation Division Agent? Reason: 4PM Day 2 Month 3 Year 62
Other well as hereafter ind Was any delay in plugging of Yes No X If Yes how long? Operation Completed: Hour The above well was plugged	perations caused by Conservation Division Agent? Reason: 4PM Day 2 Month 3 Year 62
Other well as hereafter ind Was any delay in plugging of Yes No X If Yes how long? Operation Completed: Hour The above well was plugged 5/8" 200' circulated	perations caused by Conservation Division Agent? Reason: 4PM Day 2 Month 3 Year 62 as follows: with cement - 5½" 3830' with 100 sax cement - 5½"
Other well as hereafter ind Was any delay in plugging of Yes No X If Yes how long? Operation Completed: Hour The above well was plugged 5/8" 200' circulated queezed at 915' with 4	perations caused by Conservation Division Agent? Reason: 4PM Day 2 Month 3 Year 62 as follows: with cement - 5½" 3830' with 100 sax cement - 5½"

Signed:

Conservation Division Agent

Reviewed: Harold Places
Field Supervisor

on top mud - squeezed - 250# pump pressure

Mudding and cementing by Knight co pump truck

Remarks:

INVOICED

DATE 3/16/62