Го:	API NUMBER	15-205- / ⁹	<u> 1486-0</u>	<u> </u>
STATE CORPORATION COMMISSION	SE NW NW	Sec/Twp/Rge Sec 3 T28S R17E		
Wichita State Office Bldg PLUGGING SECTION	4414 (gps)	4414 (gps) feet from south section line		
130 S. Market, Room 2078 Wichita, Kansas 67202	4114 (gps)	_feet from ea	ast section lir	ne ·
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Stover	STO 13 (gps	s)
Operator License #101	County	Wilson		
Operator: State Of Kansas Fee Fund	Well Total Depth	1050 est		feet
Name & Stover Lease Project	Production Pipe:	2	_Size Feet	NA
Address	Surface Casing:	6.25	_Size Feet	NA
AB oil well XXXXXX Gas Well SWI	Well/ Input Well		_ D&A	
Other well as hereinafter indicated:				
Plugging Contractor: Kepley Well Service, LLC			_ Lic. #	33749
Address: 19245 Ford Road, Chanute, Kansas 66720				
Company to plug at: Hour: Day:	4	Month:	10	2010
Plugging proposal received from: Mike Kepley				
ragging proposal rosolica noini minto respicy				
Oning and Marian Marian Mall Contine 11.0	ement.	_Phone: ,	620-431-89	945
Company Name: <u>Kepley Well Service, LLC</u> Were: <u>Clean well to TD and pump full of portland c</u>	ement.			945
Company Name: Kepley Well Service, LLC	ement.	_Phone: ,		
Company Name: <u>Kepley Well Service, LLC</u> Were: <u>Clean well to TD and pump full of portland c</u>	ement.		nning TECHNICIAN	
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland c	ement. eceived by:	Alan M. Du	nning TECHNICIAN None	xxxxxx
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland c Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day:	ement. eceived by: Part 4	Alan M. Du	nning TECHNICIAN None	XXXXXX 2010
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland c Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day:	ement. eceived by: Part 4 as washed down th	Alan M. Du Month:	nning TECHNICIAN None 10	XXXXXX 2010 on string
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland c Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: A 1" cement string was	eceived by: Part 4 as washed down th was washed down	Alan M. Du	nning TECHNICIAN None 10 the production	XXXXXX 2010 on string
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland completed by Agent: Operations Completed: Hour: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string	eceived by: Part 4 as washed down th was washed down ht from btm to top th	Alan M. Du	nning TECHNICIAN None 10 the production f the production	XXXXXX 2010 on string
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland completed: Plugging Proposal Recompleted: Hour: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string string to 1020'. The well was then pumped full of cements.	eceived by: Part 4 as washed down th was washed down ht from btm to top th	Alan M. Du	nning TECHNICIAN None 10 the production f the production	XXXXXX 2010 on string
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland completed: Plugging Proposal Recognitions Completed: Hour: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string string to 1020'. The well was then pumped full of cement A total of 86 sacks of portland cement were used to plug	eceived by: Part 4 as washed down th was washed down ht from btm to top th	Alan M. Du	nning TECHNICIAN None 10 the production f the production ment strings. ow plow dep	XXXXXX 2010 on string
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland company Plugging Proposal Reservices All Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string string to 1020'. The well was then pumped full of cement A total of 86 sacks of portland cement were used to plug and the location restored.	eceived by: Part 4 as washed down th was washed down ht from btm to top th	Alan M. Du	nning TECHNICIAN None 10 the production f the production ment strings. ow plow dep	XXXXXX 2010 on string ion th
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland completed: Plugging Proposal Recognitions Completed: Hour: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string string to 1020'. The well was then pumped full of cement A total of 86 sacks of portland cement were used to plug	eceived by: Part 4 as washed down th was washed down at from btm to top th g well. The well wa	Alan M. Du	nning TECHNICIAN None 10 the production f the production ment strings. ow plow dep	XXXXXX 2010 on string ion th RECEIVEL
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland completed: Plugging Proposal Research Plugging attended by Agent: All Department Service Completed: Hour: Day: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string string to 1020'. The well was then pumped full of cement A total of 86 sacks of portland cement were used to plugging and the location restored. Remarks: Control #20110002-013 (If additional description is necessary, users)	eceived by: Part 4 as washed down th was washed down at from btm to top th g well. The well wa	Alan M. Du	nning TECHNICIAN None 10 the production f the production ment strings. ow plow dep	XXXXXX 2010 on string ion th
Company Name: Kepley Well Service, LLC Were: Clean well to TD and pump full of portland c Plugging Proposal Re Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: A 1" cement string was to 2' where the pipe hit cement. A 2nd 1" cement string was to 1020'. The well was then pumped full of cement A total of 86 sacks of portland cement were used to plug and the location restored. Remarks: Control #20110002-013	eceived by: Part 4 as washed down th was washed down at from btm to top th g well. The well wa	Alan M. Du	nning TECHNICIAN None 10 the production f the production ment strings. ow plow dep	xxxxxx 2010 on string ion th