Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

Nama. Linn Oper						378(- 00-00
Name: Linn Operating Inc Address 1: 600 Travis Suite 5100					otion:	
Address 1:600 Tra	vis Suite 510	0		222		Twp. 30 S. R. 7 East X
Address 2:			·	330 Feet from North / X South Line of Sect		
City: Houston State: TX Zip: 77002+				1980 Feet from X East / West Line of Sect		
Contact Person: <u>Rena</u> Phone: (<u>405</u>) <u>241</u> -	Carter					arest Outside Section Corner:
					_	X SE SW
	Oil Well X Gas Well			County:	Kingman	
	Other:		1 1			nson A Well#1
	Gas Stor			Date Well Co	ompleted: 9-7	-83
Is ACO-1 filed? X Yes [<u> </u>		∆ No ·	The plugging	g proposal was ap	proved on: 12-23-10 (I
Producing Formation(s): List Miss Depth		sheet) m: 4203 _{T.D.} 427	<u>م</u> ا	,	eve VanGe	
	•			Plugging Co	mmenced: 12	=23=10
	to Top: Botton to Top: Botton	m: T.D	1 1	Plugging Co	mpleted: 12-	-29-10
Deptin	to top: Botton	n: i.U				
Show depth and thickness of	f all water, oil and gas forma	tions.	-			
Oil, Gas or Wate	er Records		Casing Red	cord (Surface	e, Conductor & Prod	duction)
Formation	Content	Casing	Size		Setting Depth	Pulled Out
Miss	Oil Gas Water	Surface	8 5	/8	249	-0-
		Production	4 1	/2	4269	1293
	,	· -				nods used in introducing it into the hol
Describe in detail the manne cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut	wised, state the character of sunit, Winds & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee	same depth placed from (b y/2sx cement, o k cement 1300' k cement 350' to el ID plate 4'	cut & p to 110 to surf. BGL	ull 4 1 0', Tag ace,	lugset. 1/2" casir g at 1047'	ng at 1293', RIHW to RECE!
Describe in detail the manner cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut	wised, state the character of sunit, Winds & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee	same depth placed from (b v/2sx cement, o c cement 1300' c cement 350' el ID plate 4'	cut & p to 110 to surf. BGL	ull 4 1 0', Tag ace,	lugset. 1/2" casir g at 1047'	ng at 1293', RIHW to RECE!
Describe in detail the manner cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut	used, state the character of sunit, W rods & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee #: 8733	same depth placed from (b y/2sx cement, o k cement 1300' k cement 350' to el ID plate 4'	cut & p to 110 to surf. BGL Name:	ull 4] 0', Tag ace,	lugset. 1/2" casir g at 1047'	ng at 1293', RIHW to RECE!
Describe in detail the manne cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut Plugging Contractor License Address 1: PO Box	used, state the character of sunit, W rods & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee #: 8733	same depth placed from (b v/2sx cement, o k cement 1300' k cement 350' el ID plate 4'	cut & p to 110 to surf. BGL Name:	ull 4] 0', Tag ace,	l/2" casir g at 1047'	ng at 1293', RIHW to RECE!
Describe in detail the manne cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut Plugging Contractor License Address 1: PO Box City: Enid	unit, W rods & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee #: 8733	same depth placed from (b y/2sx cement, o k cement 1300' k cement 350' el ID plate 4'	cut & p to 110 to surf BGL Name:	ull 4] O', Tag ace, Jerry [l/2" casir g at 1047' Dunkin INC	ng at 1293', RIHW to Pump 35sx cement RECE!
Describe in detail the manner cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut	used, state the character of sunit, W rods & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee #: 8733 389 6152 for Plugging Fees: Linn	same depth placed from (by v/2sx cement, or cement 350' to cement	cut & p to 110 to surf BGL Name:	ull 4 1 0', Tag ace, Jerry [State: Ok	l/2" casir g at 1047' Dunkin INC	ng at 1293', RIHW to Pump 35sx cement RECE!
Describe in detail the manne cement or other plugs were to 12-23-10 MIRU 12-27-10 POOH 12-28-10 Set to 1 to 6 12-29-10 Cut	used, state the character of sunit, W rods & tubing CIBP at 4100' w 700', Pump 50sx 50', Pump 135sx off & weld stee #: 8733 389 6152 for Plugging Fees: Linn	same depth placed from (b y/2sx cement, o k cement 1300' k cement 350' el ID plate 4'	cut & p to 110 to surf BGL Name:	ull 4] 0', Tag ace, Jerry [l/2" casir g at 1047' Dunkin INC	ng at 1293', RIHW to Pump 35sx cement RECE!