## KCC OIL/GAS REGULATORY OFFICES

Date: 04/01/11	District: 1		Case #:
	New Situ	uation	Lease Inspection
	Respons	e to Request	Complaint
	Follow-U	U <b>p</b>	Field Report
Operator License No: 31930	API Well Number: <u>15-057-20717-00-00</u>		
Op Name: Blueridge Petroleum Corporation	Spot: <u>SW-N</u>	IE-NE-NE	Sec 9 Twp 27 S Rng 24 E / W
Address 1: P.O. Box 1913	335		Feet from N/ S Line of Section
Address 2:	585		Feet from E/E / W Line of Section
City: Enid	GPS: Lat: <u>37</u>	7.72028	Long: <u>99.94474</u> Date: <u>4/1/11</u>
State: OK Zip Code: <u>73702 -1913</u>	Lease Name:	Blackfoot	Well #: <u>4-9</u>
Operator Phone #: (580) 242-3732	County: For	rd	
Reason for Investigation:			
Company requested a state witness to te alternate II cementing job.			
Problem:			
Alternate II cementing requirements have not been met.			
Alternate in Cementing requirements have not been met.			
Persons Contacted:			
Dalton Popp.			
Findings:			
8 5/8" was set @ 420'. 5 1/2" was set @ 5099' with 125 sx cement on primary cementing job. Company opened port collar @ 1556'. Swift Services, Inc. pumped 150# hulls & 200 sx SMD cement, with zero returns. Closed port collar. Company has loggers scheduled for Monday.  4/4/11 Bond log showed TOC @ 1050'. Perforated casing @ 1000' - no blow - pumped 20 sx gel @ 600# with slight blow. Pump 125 sx cement, shut down for 30 minutes. Pumped 75 sx cement with no blow or circulation. Will run Temperature log in the morning.  4/5/11 Temp. log showed TOC @ 770', with shale sluff @ 580 - 650'. Perforated @ 550'. Swift Services, Inc. pumped 140 sx SMD cement, circulating 20 sx to the pit.			
Action/Recommendations: Follow Up Required Yes No Date:			
None. Alternate II cementing requirements have been met.  RECEIVED			RECEIVED
			APR 2 1 2011
	·		KCC WICHITA
Verification Sources:			Photos Taken: 0
RBDMS KGS	TA Program	<i></i> . •	
	Courthouse	By: <u>Eu</u>	Muxa
Other: On-site witness.		Eric	MacLaren, Steve Durrant.
Retain 1 Copy District Office Send 1 Copy to Conservation Division			

Form: