Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

the same are true and correct, so help me God.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

API No. 15 - 003 - 21465 -00 -00 OPERATOR: License #: 33097 Name: Son thern Star Central GAS Pipeline Address 1: 4700 Hwy 56 P.O. Box 20010 & S. R. 19 Least West Feet from North South Line of Section Address 2: ________ State: KY Zip: 42304 + ____ Feet from East West Line of Section Contact Person: Mark Rouse Footages Calculated from Nearest Outside Section Corner: Phone: (270) 852-4490 NE NW SE SW County: Anderson Lease Name: Benjamin - OHO Well #: 13 Water Supply Well Other: SWD Permit #:____ Gas Storage Permit #: __ Date Well Completed: 9-3-81 ENHR Permit #: The plugging proposal was approved on: 6-30-10 (Date) Is ACO-1 filed? Yes No If not, is well log attached? Yes No by: Steve Bond (KCC District Agent's Name) Producing Formation(s): List All (If needed attach another sheet) Squirred Depth to Top: 826' Bottom: 853' T.D. 890' Plugging Commenced: 12-3-10 Bottom: _____T.D. __ Depth to Top: _____ Plugging Completed: 12-3-10 Bottom: ______T.D. __ Depth to Top: _____ Show depth and thickness of all water, bil and gas formations. Casing Record (Surface, Conductor & Production) Oil. Gas or Water Records Setting Depth Pulled Out Casing Content Formation Surface Squirrel Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Washed I" down to 825', pumped cement to surface, pulled pipe, and topped well off RECEIVED Squeezed coment into formation, and shot in at 500 psi. JAN 20 2011 40 sades used. KCC WICHITA Plugging Contractor License #: 6372 Name Splane Pulling & Roustabout Services, INC. Address 1: P.O. Box 386 City: Chanute Phone: (620) 431-1359 Name of Party Responsible for Plugging Fees: Southern Star State of Kentucky Employee of Operator or Operator on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and