Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Ritchie Exploration, Inc.	License Number: 4767
Operator Address: P. O. Wichita 783188, Wichita, KS 67278-3188	
Contact Person: Peter Fiorini	Phone Number: (316) 691 - 9500
Permit Number (API No. if applicable): 15-163-22925-00-002	Lease Name & Well No.: R V Jones #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NE NW SW SW
Settling Pit Drilling Pit	Sec. 6 Twp. 7S R. 20 East West
✓ Workover Pit	1077 Feet from North / South Line of Section
	4920 Feet from ✓ East / West Line of Section
	Rooks County
Date of closure: 05/24/2010	
Was an artificial liner used? ✓ Yes No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
n not now more and sides and section section to prevent dominate inigration of the pic contents:	
n non non non and and and and an	
m non non non and and and and and and and and and an	DEan.:
	RECEIVED
Abandonment procedure of pit: Backfill and level as close as possible to its natural state.	
Abandonment procedure of pit:	RECEIVED JUL 0 9 2010 KCC WICHITA
Abandonment procedure of pit:	
Abandonment procedure of pit:	JUL (1 9 2010 KCC WICHITA Beologist for Ritchie Exploration, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Production/Development G	JUL (1 9 2010 KCC WICHITA Beologist for Ritchie Exploration, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Production/Development G	JUL (1 9 2010 KCC WICHITA Beologist for Ritchie Exploration, Inc. (Co.),
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Production/Development G	JUL (1 9 2010 KCC WICHITA Seologist for Ritchie Exploration, Inc. (Co.), a best of his her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Backfill and level as close as possible to its natural state. The undersigned hereby certifies that he / she is Production/Development G a duly authorized agent, that all information shown hereon is true and correct to the	JUL (1 9 2010 KCC WICHITA Seologist for Ritchie Exploration, Inc. (Co.), a best of his her knowledge and belief. Signature of Applicant or Agent