Form CP-3 Rev. 6-4-68

## KANSAS

CONSERVATION DIVISION AGENT'S REPORT RECEIVED COMMISSION STATE CORPORATION COMMISSION

J. Lewis Brock Administrator 245 North Water Wichita, KS 67202

NG 0 8 1977 API Number 15 - 051-21,354 -

Operator's Full Name	Ernst & Steinle Oper.
Complete Address	1025 Main, Russell, Kansas
Lease Name	Rohleder Well No. 1
Location	SE NW NE Sec. 17 Twp. 14 Rge. (E) (W
County	Ellis Total Depth 3150.
Abandoned Oil Well	Gas Well Input Well SWD Well D & A X
Other well as hereafter	ndicated
Plugging Contractor	Emphasis Drlg.
Address	Russell, Kansas License No.
	1017
The above well was plugg	Hour #↓P Day 4 Month 8 Year 1977  ed as follows: t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.
The above well was plugg	ed as follows: t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel. heavy mud, set 50 sk cmt plug at 500° thru drill pipe.
The above well was plugg RTD 3150° 8 5/8 csg se Gunned pits, circulated	ed as follows: t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.
The above well was plugg RTD 3150° 8 5/8 csg se Gunned pits, circulated	ed as follows:  t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.  heavy mud, set 50 sk cmt plug at 500° thru drill pipe.  sk cmt plug thru drill pipe. Heavy mud to 40° set solid
The above well was plugg RTD 3150° 8 5/8 csg se Gunned pits, circulated Heavy mud to 210° set 29	ed as follows:  t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.  heavy mud, set 50 sk cmt plug at 500° thru drill pipe.  sk cmt plug thru drill pipe. Heavy mud to 40° set solid
The above well was plugg RTD 3150° 8 5/8 csg se Gunned pits, circulated Heavy mud to 210° set 29	ed as follows:  t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.  heavy mud, set 50 sk cmt plug at 500° thru drill pipe.  sk cmt plug thru drill pipe. Heavy mud to 40° set solid
The above well was plugg RTD 3150° 8 5/8 csg se Gunned pits, circulated Heavy mud to 210° set 29	ed as follows:  t 214° cwc 150 sk. Plg. Mat. 50-50 poz 2% total gel.  heavy mud, set 50 sk cmt plug at 500° thru drill pipe.  sk cmt plug thru drill pipe. Heavy mud to 40° set solid