Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

	30606		API	No. 15 - <u>025+2067</u>	1-0000						
Name:Murfin_Drilling_Co., Inc			Spo	Spot Description: S/2 SW NE							
Address 1: 250 N. Water, Suite 300				Sec. 3 Twp. 30 S. R. 25 East West							
Address 2:				_2,310 Feet from 🕡 North / 🗌 South Line of Section							
City: Wichita State: Ks. zip: 67202 +			_1.								
Contact Person: James Esquiyal				Footages Calculated from Nearest Outside Section Corner:							
Phone: (620) 277-0				NE NW	SE Sw						
		ell OG D&A Cati		nty: Clark							
Water Supply Well Other: SWD Permit #: ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? Yes No If not, is well log attached? Yes No Producing Formation(s): List All (If needed attach another sheet)				Lease Name: _Minneola_Unit							
									by:	Jerry Stapelton	(KCC District Agent's Name,
						Depth to Top: Bottom: i.D				Plugging Commenced: 2-9-10	
Depth		Bottom: T.D	Plun	Plugging Completed:2-10-10							
Ueptr	то юр:	Bottom:T.D									
Show depth and thickness of	of all umter all and man	formations									
		Tormations.									
Oll, Gas or Wa	-, 			(Surface, Conductor & Proc							
Formation	Content	Casing	Size	Setting Depth	Pulled Out						
			8-5/8"	679'	None						
			E 4/09	54451	0500						
			5-1/2"	5415'	2528'						
	1										
ement or other plugs were	used, state the charac	ter of same depth placed from (bottom), to (top) for	each plug set.	nods used in introducing it into the hole. If						
Plugged off botto 1560', Pumped 1 up to 360', pumpe	m with sand to 5 sacks gel ar 20 30 sacks ce	ter of same depth placed from (o 5200' and 5 sacks nd 50 sacks cement	cement. Cu , pulled up to	each plug set. It casing loose @ o 700', pumped :	2528', pulled up to 50 sacks cement, pulled acks cement, pulled ocks cement, pulled ocks cement, for pos,						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging	m with sand to 15 sacks gel ar ed 30 sacks ce Complete.	ter of same depth placed from (o 5200' and 5 sacks nd 50 sacks cement ement, pulled up to 4	cement. Cu , pulled up to 10' and topp	each plug set. It casing loose @ o 700', pumped : ed off with 40 sa	2528', pulled up to 50 sacks cement, pulled						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging	m with sand to 5 sacks gel ared 30 sacks cel Complete.	ter of same depth placed from (o 5200' and 5 sacks nd 50 sacks cement ement, pulled up to 4	cement. Cu , pulled up to lo' and topp	each plug set. It casing loose @ o 700', pumped : ed off with 40 sa	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos,						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging	m with sand to 15 sacks gel ar ed 30 sacks ce Complete. #:31529	ter of same depth placed from (5 5200' and 5 sacks dement and 50 sacks dement ement, pulled up to 4	cement. Cu , pulled up to , pulled up to , and topp Name: Mik	each plug set. It casing loose @ 0 700', pumped e ed off with 40 sa	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos,						
Plugged off botto 1560', Pumped 1 up to 360', pumped 1% gel. Plugging lugging Contractor License ddress 1: P.O. Box 4 ity: Chase	m with sand to 15 sacks gel ar 26 30 sacks ce Complete. #: 31529	ter of same depth placed from (5 5200' and 5 sacks dement and 50 sacks dement ement, pulled up to 4	cement. Cu , pulled up to , pulled up to , and topp Name: Mik	each plug set. It casing loose @ 0 700', pumped e ed off with 40 sa	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos,						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging Plugging Contractor License address 1: P.O. Box 4 sity: Chase	m with sand to 5 sacks gel ar ed 30 sacks ce Complete. 31529	ter of same depth placed from (5 5200' and 5 sacks dement and 50 sacks dement ement, pulled up to 4	cement. Cu , pulled up to 10' and topp Name: Mik Address 2:	each plug set. It casing loose @ o 700', pumped ed off with 40 sa e's Testing & Salv Kansas	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos, // // // // // // // // // // // // //						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging Plugging Contractor License Address 1: P.O. Box 4 City: Chase Phone: (620) 938-2	m with sand to 5 sacks gel ar ed 30 sacks ce Complete. 31529 167 943 for Plugging Fees:M	ter of same depth placed from (5 5200' and 5 sacks nd 50 sacks cement ement, pulled up to 4	cement. Cu pulled up to or and topp Name: Mik Address 2:	each plug set. It casing loose @ o 700', pumped ed off with 40 sa e's Testing & Salv Kansas	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos, // // // // // // // // // // // // //						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging Plugging Contractor License Address 1: P.O. Box 4 City: Chase Phone: (620) 938-2 Jame of Party Responsible in the of Kansas	m with sand to 5 sacks gel ar ed 30 sacks ce Complete. 31529 467 943 for Plugging Fees:M	ter of same depth placed from (5 5200' and 5 sacks nd 50 sacks cement ement, pulled up to 4 lurfin Drilling Co., Inc., nty, Rice	cement. Cu pulled up to or and topp Name: Mik Address 2:	each plug set. It casing loose @ 0 700', pumped a ed off with 40 sa e's Testing & Salv Kansas	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos, // // // // // // // // // // // // //						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging Plugging Contractor License Address 1: P.O. Box 4 City: Chase Phone: (620) 938-2 Jame of Party Responsible in the state of Kansas Mike Kelso eing first duly sworn on oath	with sand to sacks gel ared 30 sacks cel ared 30 sacks cel ared 30 sacks cel ared 31529 167 1943 167 1943 167 167 17943 17943 18943 18943 18943 18943 18943 18943 18943	ter of same depth placed from (a) 5200' and 5 acks acks and 50 sacks dement ement, pulled up to 4 lurfin Drilling Co., Inc., acks.	notiom), to (top) for cement. Cut, pulled up to 10' and topp Name: Mik Address 2: State:	each plug set. It casing loose (co 700', pumped ed off with 40 sate) e's Testing & Salve Kansas	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos, // // // // // // // // // // // // //						
Plugged off botto 1560', Pumped 1 up to 360', pumpe 4% gel. Plugging Plugging Contractor License Address 1: P.O. Box 4 City: Chase Phone: (620) 938-2 Hame of Party Responsible in the contractor License State of Kansas Mike Kelso	with sand to sacks gel ared 30 sacks cel ared 30 sacks cel ared 30 sacks cel ared 31529 167 1943 167 1943 167 167 17943 17943 18943 18943 18943 18943 18943 18943 18943	ter of same depth placed from (a) 5200' and 5 acks acks and 50 sacks dement ement, pulled up to 4 lurfin Drilling Co., Inc., acks.	notiom), to (top) for cement. Cut, pulled up to 10' and topp Name: Mik Address 2: State:	each plug set. It casing loose (co 700', pumped ed off with 40 sate) e's Testing & Salve Kansas	22528', pulled up to 50 sacks cement, pulled acks cement, 60/40 pos, // // // // // // // // // // // // //						