KCC OIL/GAS REGULATORY OFFICES

oto: 06/06/11	District: 01	Case #:
nte: <u>06/06/11</u>	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow-Up	Field Report
erator License No: 3842	API Well Number: 15-10	1-22292-00-00
Name: Larson Engineering, Inc. dba Larson Operating Company	Spot: <u>NW SW NW SE</u>	_ Sec <u>32</u> Twp <u>17</u> S Rng <u>28</u> E / \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
dress 1: <u>562 W State Rd.4</u>	1,800	Feet from N/ S Line of Section
dress 2:	2,475	Feet from Feet from VE / W Line of Section
y: Olmitz	GPS: Lat: 38.53041	Long: 100.44007 Date: 6/6/11
te: KS Zip Code: 67564 -8561	Lease Name: <u>Joann Unit</u>	Well #: <u>1-32</u>
perator Phone #: (620) 653-7368	County: Lane	
ason for Investigation:		
lequest by company to witness Alternate II	completion.	
oblem:		
Ione: Cement circulated to surface and stay	red.	·
ersons Contacted:		
ohn Davison for Larson Engineering.	• .	
indings:		
TD @ 4,653'		
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sx		# of flo-seal with 20 sxs to pit. Cement
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sx by Swift Services.		# of flo-seal with 20 sxs to pit. Cement
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sx by Swift Services.		# of flo-seal with 20 sxs to pit. Cement
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole.	sxs cmt. s SMD cement with 1/4	
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Followith Recommendations:	sxs cmt. s SMD cement with 1/4	No 🖸 Date:
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Following Recommendations:	sxs cmt. s SMD cement with 1/4	No ☑ Date: t circulated to the surface and stayed.
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Action/Recommendations: Following Production of the production	sxs cmt. s SMD cement with 1/4	No 🖸 Date:
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Following Recommendations:	sxs cmt. s SMD cement with 1/4	No ☑ Date: t circulated to the surface and stayed. RECEIVED
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Action/Recommendations: None required. Alternate II requirements hole. RECEIVED	sxs cmt. s SMD cement with 1/4	No ☑ Date: t circulated to the surface and stayed.
S-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Action/Recommendations: None required. Alternate II requirements holds RECEIVED JUN - 9 2011	sxs cmt. s SMD cement with 1/4	Date:t circulated to the surface and stayed. RECEIVED
S-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Action/Recommendations: None required. Alternate II requirements hold. RECEIVED JUN - 9 2011	sxs cmt. s SMD cement with 1/4	No ☑ Date:t circulated to the surface and stayed. RECEIVED
None required. Alternate II requirements h RECEIVED JUN - 9 2011 Verification SourKCC DODGE CITY	sxs cmt. s SMD cement with 1/4- ow Up Required Yes ave been met. Cement	Date:
5-1/2" production casing set at 4,652' w/125 Port Collar @ 2,159', cemented with 170 sxs by Swift Services. Fritzler trucking unit over the hole. Action/Recommendations: Following Production Alternate II requirements hold production of the prod	sxs cmt. S SMD cement with 1/4 ow Up Required Yes ave been met. Cement TA Program Courthouse By: Je	Date: t circulated to the surface and stayed. RECEIVED JUN 1 5 2011 KCC WICHITA

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: <u>02/22/2008</u>

Date: 06/06/11			District:	.01	1	License #: <u>3842</u>		
Op Name: 3842			Spot: <u>N\</u>	V SW NW SE	Sec <u>32</u> Twp	17 S Rng 28		
County: Lane			Lease Na	Lease Name: Joann Unit Well #: 1-32				
I.D. Sign Yes	No		5	Gas Venting	Yes No		. 5	
	·		·			·		
Tank Battery Condition		ا اها	Pits					
Condition: Good	Questional	ble Overflov	ving	Fluid Depth: _	ft; Approx.	Size:ft. x	ft.	
Pits, Injection Site				Saltwater Pipelines				
Fluid Depth:	_ft; Approx. S	Size:f	t. xft.	Leaks Visible	e: Y N	Tested for Leaks:	Y N	
Oil Spill Evidence	·		,	Flowing Ho	les			
Abandoned Well	Potential Poll	ution Problem [Yes No 🗊	TA Wells	•			
				Monitoring	Records			
Lease Cleanliness Very Good S	atisfactory _	Poor Ver	y Bad					
SWD/ER Injection Wel	Yes _	No	Lane 🖭	Gauge Connect	ions Yes N	0	5	
Permit #: P	ressure – Actu	al: psi; Au	thorized: psi	Tubing:	T/C Annulus:	; C/SP Ann	ulus:	
Permit #: P					T/C Annulus:			
Permit #:P					; T/C Annulus: _			
Permit #:P	ressure – Actu	al:psi; Au	thorized: psi	Tubing:	T/C Annulus: _	; C/SP Ann	ulus:	
API Number	Footages	Spot Location	GPS	Well#		Well Status		
, 				į				
	1.							
; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;							-	
	, k							
					,			
i .		-			,			
							· 11-12	