A STATE OF CONTRACTOR OF A STATE	N						
Give All Information Completely		wi	ali. Pri	JGGING R	ECORD		
Make Required Affidavit Mail or Deliver Report to:	•	44.1	ابلالا بدندر	JOSETO N	LCOND,		
Conservation Division							
P. O. Box 17027		Scott	Count	v. Sec. 2	Twp.20S Rea	(E) 34(
Wichita, Kansas 67217	Location as "I	NE/CNWKSWX" o				(-)(
NORTH	Lease Owner.		e L. B	rown Com	pany		
	Lease Name	-				Well No. 1	
		Office Address 1500 Vickers/KSB&T Bldg., Wichita					
1iiii					_	y Hole	
		Character of Well (completed as Oil, Cas or Dry Hole) Date well completed August 25, 19 7					
1 ; ;		Application for plugging filed					
		Application for plugging approved August 25, 19 7					
		menced			ugust 25	^	
		pleted			ry Hole	19	
	Reason for ab	andonment of well	or producin	g formation	ry noie		
							
1 ' !	If a producing	g well is abandone	d, date of la	ist production		19	
<u> </u>	Was permissi	on obtained from	the Conserv	ation Division	or its agents bei	fore phigging was coactor.	
Locate well correctly on above Section Plat	menced?	Yes_(Gilber	t Baltna	zor or E	Palco)	
Name of Conservation Agent who sup	pervised plugging of t	his well				······	
Producing formation.		Depth to top	Batton	·	Total Depth of	Well 5260	
Show depth and tlackness of all water					_		
•							
OIL, CAS OR WATER RECOR	DS					CASING RECORE	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED OUT	
	Surface		361	8-5/8"	361	None	
	Casing			 		 	
	- Casing		 	 	 	 	
	 			 	 	 	
	 			 	 	 	
		1	l	I	I	[
				<u> </u>	 		
	 						
Describe in detail the manner is in introducing it into the hole. If ce	ment or other plugs v						
in introducing it into the hole. If ce fect for each plug if	ment or other plugs v set. eavy Mud fr	vere used, state th	e character of	of same and dep	th placed, from		
in introducing it into the hole. If ce feet for each plug in He	ment or other plugs vect. avy Mud fr sax 50/50	om Total Pozmix @	Depth	to /00 F	reet,		
in introducing it into the hole. If ce- fect for each plug in He	ment or other plugs vect. eavy Mud fr o sax 50/50 id to 300 F	om Total Pozmix @ eet, 20 s	Depth 700 F ax 50/	to /00 Feet; Hea	reet,		
in introducing it into the hole. If ce feet for each plug in He 7 (Mu 3 (ment or other plugs veet. eavy Mud fr b sax 50/50 ad to 300 F b Feet; He	om Total Pozmix @ eet, 20 s avy Mud t	Depth 700 F ax 50/	to 700 Feet; Hea 50 Pozmi	th placed, from eet, avy x @		
in introducing it into the hole. If ce- fect for each plug in He 70 Mu 30	ment or other plugs vect. eavy Mud from 300 Food to 300 Feet; He bridge & 4	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/	Depth 700 F ax 50/ 0 40 F	to 700 Feet; Hea 50 Pozmi eet, Plumix; 10	reet, avy x @ ig sax		
in introducing it into the hole. If ce- fect for each plug in He 70 Mu 30	ment or other plugs veet. eavy Mud from 50/50 ad to 300 F 00 Feet; He bridge & 4	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/	Depth 700 F ax 50/ 0 40 F	to 700 Feet; Hea 50 Pozmi	reet, avy x @ ig sax		
in introducing it into the hole. If ce- fect for each plug in He 70 Mu 30	ment or other plugs vect. eavy Mud from 300 Food to 300 Feet; He bridge & 4	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/	Depth 700 F ax 50/ 0 40 F	to 700 Feet; Hea 50 Pozmi eet, Plumix; 10	reet, avy x @ ig sax		
in introducing it into the hole. If ce- fect for each plug in He 70 Mu 30	ment or other plugs vect. eavy Mud from 300 Food to 300 Feet; He bridge & 4	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/	Depth 700 F ax 50/ 0 40 F	to 700 Feet; Hea 50 Pozmi eet, Plumix; 10	reet, avy x @ ig sax		
in introducing it into the hole. If ce- fect for each plug in He 70 Mu 30	ment or other plugs veet. eavy Mud from the sax 50/50 and to 300 Feet; He bridge & 4 ozmix 40' to see the same same same same same same same sam	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plumix; 10 ted @ 7:	reet, avy x @ ig sax		
in introducing it into the hole. If cefect for each plug is He 70 Mu 30 Experiments	ment or other plugs veet. eavy Mud from the sax 50/50 and to 300 Feet; He bridge & 4 ozmix 40' to see the same same same same same same same sam	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plumix; 10 ted @ 7:	reet, avy x @ ig sax		
in introducing it into the hole. If cefect for each plug is He 70 Mu 30 & Po Po Name of Plugging Contractor	ment or other plugs viset. eavy Mud fr 0 sax 50/50 ad to 300 F 00 Feet; He bridge & 4 ozmix 40' t	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from eet, avy x @ ig sax 45 A.M.		
in introducing it into the hole. If cefect for each plug is He 70 Mu 30 Experiments	ment or other plugs vect. eavy Mud from the sax 50/50 and to 300 Feet; Hebridge & 4 ozmix 40' to the same that th	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	reet, avy x @ ig sax		
in introducing it into the hole. If ce feet for each plug is He 70 Mu 30 & Po Name of Plugging Contractor Address	ment or other plugs vect. eavy Mud from 50/50 id to 300 F 00 Feet; He bridge & 4 ozmix 40' t (If addition Hallibur	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from eet, avy x @ ig sax 45 A.M.		
in introducing it into the hole. If cefect for each plug is He 70 Mu 30 & Po Name of Plugging Contractor Address STATE OF KANSAS	ment or other plugs viset. eavy Mud from the sax 50/50 and to 300 Feet; He bridge & 4 ozmix 40' to the same that	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112,	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ag sax 45 A.M.		
in introducing it into the hole. If cefect for each plug is He 70 Mu 30 & Po Name of Plugging Contractor Address STATE OF KANSAS	ment or other plugs vet. eavy Mud from the sax 50/50 and to 300 Feb. bridge & 4 bridge	om Total Pozmix @ Poz	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy X @ 19 Sax 45 A.M.		
in introducing it into the bole. If cefect for each plug is He 70 Mu 30 Name of Plugging Contractor Address STATE OF KANSAS T.M.McCaul, Jr. 6	ment or other plugs vect. eavy Mud from Sax 50/50 and to 300 Feb.; He bridge & 4 ozmix 40' to Hallibur R.R. #1,	om Total Pozmix @ Pozmix Pozmix @ Pozmix Pozmix @ Pozmix Pozmix @ Pozmix Pozm	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy X @ 19 Sax 45 A.M.	K 91 31 51 51 51 51 51 51 51 51 51 51 51 51 51	
Name of Plugging Contractor Address T. M. McCaul, Jr. Contractor Bridge Bret duly sworn on oath,	ment or other plugs viset. eavy Mud from the plugs viset. eavy Mud from the property of the	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job all description is necess ton Box 112, punty ofS g. CoS	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy X @ 19 Sax 45 A.M.	K 91 31 51 51 51 51 51 51 51 51 51 51 51 51 51	
in introducing it into the bole. If cefect for each plug is He 70 Mu 30 Name of Plugging Contractor Address STATE OF KANSAS T.M.McCaul, Jr. 6	ment or other plugs viset. eavy Mud from the plugs viset. eavy Mud from the property of the	om Total Pozmix @ Pozmix Pozmix @ Pozmix Pozmix @ Pozmix Po	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy X @ 19 Sax 45 A.M.	K 91 31 51 51 51 51 51 51 51 51 51 51 51 51 51	
Name of Plugging Contractor Address T. M. McCaul, Jr. Contractor Bridge Bret duly sworn on oath,	ment or other plugs viset. eavy Mud from the plugs viset. eavy Mud from the property of the	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job all description is necess ton Box 112, punty ofS g. CoS	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy X @ 19 Sax 45 A.M.	K 91 31 51 51 51 51 51 51 51 51 51 51 51 51 51	
Name of Plugging Contractor Address T. M. McCaul, Jr. of M. McCaul, Jr. of M. McCaul, Jr. of M. McCaul, Jr. of M.	ment or other plugs viset. eavy Mud from the plugs viset. eavy Mud from the property of the	movere used, state the com Total Pozmix @ eet, 20 s avy Mud to 0 sax 50/0 9. Job and description is necessary ton Solution Solu	Depth 700 F ax 50/ 0 40 F 50 Poz Comple	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ig sax 45 A.M. 67901	Kat Was X 86 X X 26 X in and and the log of	
Name of Plugging Contractor Address T. M. McCaul, Jr. of McCaul, Jr. of McCaul, Jr. of McCaul as filed and the McCaul as fil	ment or other plugs viset. eavy Mud from the plugs viset. eavy Mud from the property of the	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job all description is necess ton Box 112, DUNTY OI S G. CO. knowledge of the and correct. So a (Signature)	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ig sax 45 A.M. 67901	ita, Ks. 6	
Name of Plugging Contractor Address T. M. McCaul, Jr. of M. McCaul, Jr. of M. McCaul, Jr. of M. McCaul, Jr. of M.	ment or other plugs viset. eavy Mud fr 0 sax 50/50 id to 300 F 00 Feet; He bridge & 4 ozmix 40' t Hallibur R.R. #1. of Sage Drl at the same are true	movere used, state the com Total Pozmix @ eet, 20 s avy Mud to 0 sax 50/0 9. Job and description is necessary ton Solution Solu	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ig sax 45 A.M. 67901 - 58. avx apraisi rs herein contai y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address T. M. McCaul, Jr. of M.	ment or other plugs viset. eavy Mud fr 0 sax 50/50 id to 300 F 00 Feet; He bridge & 4 ozmix 40' t Hallibur R.R. #1. of Sage Drl at the same are true	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job DUNTY OI S G. CO. knowledge of the and correct. So series of the seri	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ig sax 45 A.M. 67901	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the property of the same are true set. eavy Mud from the property of the same are true set.	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, munty oi S g. Co	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud fr 0 sax 50/50 id to 300 F 00 Feet; He bridge & 4 ozmix 40' t Hallibur R.R. #1. of Sage Drl at the same are true	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, munty oi S g. Co	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from reet, avy x @ ig sax 45 A.M. 67901 - 58. avx apraisi rs herein contai y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the property of the same are true set. eavy Mud from the property of the same are true set.	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, munty oi S g. Co	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the property of the same are true set. eavy Mud from the property of the same are true set.	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, munty oi S g. Co	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the plugs viset. detail to 300 F port of Feet; He pridge & 4 port of Feet; He	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, DUNTY OI	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the plugs viset. detail to 300 F port of Feet; He pridge & 4 port of Feet; He	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, DUNTY OI	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Name of Plugging Contractor Address STATE OF KANSAS T M. McCaul, Jr. of seath being first duly sworn on oath, above described well as filed and the system of the seath of	ment or other plugs viset. eavy Mud from the plugs viset. detail to 300 F port of Feet; He pridge & 4 port of Feet; He	om Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, DUNTY OI	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	
Address STATE OF KANSAS T. M. McCaul, Jr. Completed being first duly sworn on oath, above-described well as filed and the state of th	ment or other plugs viset. eavy Mud from the plugs viset. detail to 300 F port of Feet; He pridge & 4 port of Feet; He	m Total Pozmix @ eet, 20 s avy Mud t 0 sax 50/ o 9. Job and description is necess ton Box 112, munty oi S g. Co	Depth 700 F ax 50/ 0 40 F 50 Poz Comple Liber EDGWIC	to /00 Feet; Hea 50 Pozmi eet, Plu mix; 10 ted @ 7:	th placed, from Peet, Avy x @ Ig sax 45 A.M. 67901 ss. bir's herein contains y., Wich: (Address)	ita, Ks. 6	

SEP 1 0 1975 O-10-75 conservation dans on Wichite, Kenses

DRILLERS LOG

J. LANG NO. 1

CASING RECORD:

OPERATOR:

Maurice L. Brown Co.

DESCRIPTION:

8-5/8" set @ 361'

CONTRACTOR: Sage Drilling Co.

C NE NE

w/300 sax cement

Sec. 2-20S-34W

COMMENCED: August 4, 1975

Scott Co., Kansas

TOTAL DEPTH:

52601

COMPLETED: August 25, 1975

ELEVATION: 3013KB

FORMATION	FROM	TO	REMARKS
Surface Soil	O	395	
Sand & Shale	395	650	
Shale	650	1415	
Shale & Sand	1415	1920	
Shale	1920	2515	
Shale & Lime	2515	2705	
Lime	2705	2840	
Lime & Shale	2840	3780	
Shale	3780	3915	
Shale & Lime	3915	4150	
Lime	. 4150	4495	
Shale	4495	4510	
Lime	4510	5260	D&A

I certify that this is a true and correct copy of the above log to the best of my knowledge.

SAGE DRILLING CO., INC.

subscribed and sworn to before me this 2nd day of September, 1975.

Whitted, Notary Public

My commission expires: November 26, 1978.

SEP 1018/3