STATE CORPORATION COMMISSION

API NUMBER	15-071-2	20,71	2-00	-00			
APP. NE NW NW	SEC.	26	. Т	16	S. R	42	W

CONSERVATION DIVISION - PLUGGING SECTION 330 FEET FROM NORTH SECTION LINE
WICHITA STATE OFFICE BLDG., 130 S. MARKET1130FEET FROM WEST SECTION LINE
WICHITA, KANSAS 67202 LEASE NAME KRISS WELL # 3-26
TECHNICIAN'S PLUGGING REPORT COUNTY GREELEY
TECHNICIAN'S PLUGGING REPORT OPERATOR LICENSE # 3581 OPERATOR LICENSE # 3581 OPERATOR LICENSE # 3581 FEET
OPERATOR: RED OAK ENERGY INC. PRODUCTION CSG: SIZE " FEET "
NAME AND 7701 E KELLOGG, SUITE 710 SURFACE CASING: SIZE 850" @ 366' WITH SX
ADDRESS <u>WICHITA, KS 67207</u>
ABANDONED OIL WELLGAS WELLINPUT WELLSWD WELLD/AX
OTHER WELL AS HEREINAFTER INDICATED
PLUGGING CONTRACTOR MURFIN DRILLING COMPANY, INC LICENSE NUMBER 30606
ADDRESS _ 250 N WATER, SUITE 300, WICHITA, KS 67202
COMPANY TO PLUG AT: HOUR: 12:01 PM DAY: 24 MONTH: 10 YEAR: 1999
PLUGGING PROPOSAL RECEIVED FROM BERNIE
(COMPANY NAME) MURFIN DRILLING COMPANY, INC (PHONE) 316-267-3241
WERE:
PROPOSED METHOD OF PLUGGING SAME AS ACTUAL METHOD.
PLUGGING PROPOSAL RECEIVED BY STEVE DURRANT
TOOOTNO TROPOSED RECEIVED BY BURGAY
PLUGGING OPERATIONS ATTENDED BY AGENT?: ALLPARTXNONE
OPERATIONS COMPLETED: HOUR: 4:25 PM DAY: 25 MONTH: 10 YEAR: 1999
ACTUAL PLUGGING REPORT
SEE ATTACHED PAGE.
ACCENSON STATE CONTROL TO A COMMENTANCE TO COMENTANCE TO COMMENTANCE TO COMMENTANCE TO COMMENTANCE TO COMMENTAN
12/7/99
60020
PV. NO. OO 108 CONSTRUCTION WITH 28 CC BY ALLIED.
(IF ADDITIONAL DESCRIPTION IS NECESSARY, USE BACK OF THIS FORM.)
··· · · · · · · · · · · · · · · ·

I DID NOT OBSERVE THIS PLUGGING.

(TECHNICIAN) FORM

FORM CP-2/3

15-071-20712-00-00

Plugging procedure for Kriss #3-26 Greeley County

On 10/24/99 lost circulation at 1733' and 2587'.

1st plug at 2600' with 50 sx 60/40 pozmix 3-2cc 1/4# flo seal.

2nd plug at 1880' with 80 sx cement. Wait on location for 4 hours.

3rd plug at 1880' with 80 sx cement.

4th plug at 1880' with 75 sx ASC cement.

5th plug at 1880' with 75 sx ASC cement.

10/25/99

6th plug Bridge at 2068'. Fill hole with mud. lcm 16-20#'s. Circulate with 75 bbl. Pump 50 sx ASC with 2% cc at 1880'. Wait on location for 1 hour. Filled hole,1" to fill and circulate. 7th plug at 1200' with 50 sx ASC 2% cc cement. 8th plug at 390' with 50 sx cement. 9th plug at 40-0' with 10 sx cement. 10th plug to circulate rat hole with 15 sx cement. 11th plug to circulate mouse hole with 10 sx cement.

ATCOINED

限的 -- 2 1959

Charle Tange