KCC OIL/GAS REGULATORY OFFICES

| Date: <u>09/19/11</u> | District: 1 | Case #: | |
|--|---|--------------------|--|
| | New Situation | Lease Inspec | etion |
| | Response to Request | Complaint | |
| | Follow-Up | Field Report | 1 |
| Operator License No: 4058 | API Wall Number 15 Of | 7 207 13.00 00 | |
| Op Name: American Warrior, Inc. | API Well Number: <u>15-05</u> Spot: <u>NE-NE-NW-SE</u> | . • | |
| Address 1: 3118 Cummings Rd. | 2499 | | |
| Address 2: P.O. Box 399 | 1536 | | ─ |
| City: Garden City | GPS: Lat: | <u> </u> | |
| State: KS Zip Code: 67846 -0399 | Lease Name: Linlor A | | |
| Operator Phone #: (620) 275-2963 | County: Ford | | ····· |
| Reason for Investigation: | | | |
| Company requested a state witness to the al | ternate II cementing iol | | |
| | | | |
| Problem: | | | |
| Alternate II cementing requirements have not | t been met. | | |
| · | | | |
| Persons Contacted: | | | |
| Joe Smith. | | | |
| Findings: | | | |
| 8 5/8" was set @ 428' with 300 sx cement. 5 | 1/2" was set @ 5169' | with 125 sx cement | on primary |
| cementing job. Company opened port collar | @ 1442'. Swift Service | | |
| circulating 15 sx to the pit. Closed port collar | • | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Action/Recommendations: Follow | v Up Required Yes 🚺 | o 🖸 Date: | |
| None. Alternate II cementing requirements h | nave been met. | | RECEIVED |
| GPS converted footages are 2510' FSL & 15 | 41' FFI | | |
| | | | OCT 2 4 2011 |
| | | | KCC WICHITA |
| Verification Sources: | | | Photos Taken: 0 |
| RBDMS KGS | TA Program | - m. 1 | |
| | Courthouse By: 5 | Mukan | |
| Other: On-site witness RECEIVED | Eric | MacLaren | |
| Retain 1 Copy District Office | | | M |
| Send 1 Copy to Conservation Division | | | Form: |