KCC OIL/GAS REGULATORY OFFICES

| Date: 10/13/11 | District: 1 | Case #: |
|--|--|---|
| | New Situation | Lease Inspection |
| | Response to Request | Complaint |
| | Follow-Up | Field Report |
| | L. . | |
| Operator License No: <u>4767</u> | API Well Number: <u>15-057-20752</u> | 2-00-00 |
| Op Name: Ritchie Exploration, Inc. | Spot: <u>SW-NW</u> Sec <u>10</u> | Twp <u>28 S Rng 22 </u> |
| Address 1: 8100 E. 22nd St. N. #700 | _1930 | Feet from N/ S Line of Section |
| Address 2: <u>Box 783188</u> | .550 | Feet fromE / W Line of Section |
| City: Wichita | GPS: Lat: <u>37.62581</u> Long: <u>9</u> | 9.72007 Date: 10/13/11 |
| State: KS Zip Code: <u>67278 –3188</u> | Lease Name: <u>Derstein 10BC</u> | Well #: 1 |
| Operator Phone #: (316) 691-9500 | County: Ford | |
| Reason for Investigation: | | |
| Company requested a state witness to the a | Iternate II cementing job. | |
| Problem: | | |
| <u> </u> | | |
| Alternate II cementing requirements have no | t been met. | |
| | | |
| Persons Contacted: | | |
| Gary Rowe. | | |
| | | |
| Findings: | | |
| 8 5/8" was set @ 356' with 250 sx cement. 5 job. Company opened port collar @ 1338'. gel, 1/4# floseal cement, with 100# hulls, circ | Basic Energy Services, L.C. pu | mped 400 sx of 60/40 poz, 6% |
| Action/Recommendations: Follo None. Alternate II cementing requirements | w Up Required Yes ✔No 🖭 | Date: |
| Trong. Alternate is comenting requirements | navo boon mot. | RECEIVED |
| GPS converted footages are 1944' FNL & 568' FWL. | | 1 |
| | | OCT 2 4 2011 |
| | | KCC WICHITA |
| Verification Sources: | | Photos Taken: 0 |
| RBDMS KGS | TA Program | |
| T-1 Database District Files | Courthouse By: | |
| Other: On-site witness. | Eric MacLa | ren \ |
| Retain I Copy District Office | • | \mathcal{U} |
| Send I Copy to Conservation Division OCT 18 2011 | | Form: |

KCC DODGE CITY