KCC OIL/GAS REGULATORY OFFICES

Date: 10/14/11	District: _1	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow-Up	Field Report
Operator License No: 4058	API Well Number: 15-05	57-20750-00-00
Op Name: American Warrior, Inc.		Sec13Twp27S_Rng22E_/W
Address 1: 3118 Cummings Rd.		Feet from N/S Line of Section
Address 2: P.O. Box 399		Feet from E / W Line of Section
City: Garden City		Long: 99.68333 Date: 10/14/11
State: KS Zip Code: 67843 -0399		C Well #: 3
Operator Phone #: (620) 275-2963		
Reason for Investigation:		
Company requested a state witness to the al	ternate II cementing jo	b
Problem:		
Alternate II cementing requirements have not	t been met.	
Persons Contacted:		
Joe Smith.		
Findings:		
8 5/8" was set @ 430' with 260 sx cement. 5 1/2" was set @ 5793' with 150 sx cement on primary cementing job. Company opened port collar @ 1419'. Swift Services, Inc. pumped 170 sx SMD cement with limited returns. Cement did not circulate. 10/17/11 Steve Durrant witnessed Log Tech's bond log, and found top of cement to be around 550'. Swift Services pumped 15 sx cement down the annulus and pressured to 500#.		
Action/Recommendations: Follow	v Up Required Yes V	o Date:
None. Alternate II cementing requirements h	nave been met.	
Verification Sources:		Photos Taken: 0
✓ RBDMS KGS	ΓA Program	
	Courthouse By:	in Mulan
Other: On-site witness.	<u>Eri</u>	c MacLaren
Retain 1 Copy District Office		RECEIVED
Send 1 Copy to Conservation Division	•	Form:
		NOV 1 8 2011

KCC WICHITA