

KCC OIL/GAS REGULATORY OFFICE

15-171-20482-00-06

ALTZ

DATE 5/16/96

New Situation  
 Response to Request  
 Follow-up

OPERATOR Slawson Exploration Co. # 3988

NAME 621 N. Robinson, Ste. 490

LOCATION SE NW SW, SEC 27, T 17 S, R 31 W

& ADDRESS Oklahoma City, OK 73102

LEASE Gruver "P" Well # 2

PHONE NO. \_\_\_\_\_  
OPER. 405-232-0201 OTHER \_\_\_\_\_

COUNTY Scott API# 15-171-20,482

REASON FOR INVESTIGATION: The company attempted to complete the Alternate II cementing on 5/12/95. Cement did not circulate.

LEASE INSPECTION

PROBLEM: The Alternate II cementing requirements had not been completed.

PERSON(S) CONTACTED: \_\_\_\_\_

FINDINGS: On 5/15/95, I witnessed a bond log on this well. The bond log showed scattered cement from the port collar at 2280' to 700'. At this time the company perforated the casing at 650-652'.

COMPLAINT

On 5/16/96 the company called, reporting that cement circulated to surface, completing the job. I was unable to witness it due to witnessing a plug job on another lease.

STATE RECEIVED  
MAY 22 1995  
CONSERVATION DIVISION  
WICHITA, KANSAS  
05-22-95

photos taken: \_\_\_\_\_

ACTION/RECOMMENDATIONS: The Alternate II cementing is completed. Case closed.

FIELD REPORT

Retain 1 copy Joint District Office  
Send 1 copy Conservation Division

By Richard W. Lacey

5/16/95