To:	API NUMBER	15-205-	1023-0	<u>0-00</u>
STATE CORPORATION COMMISSION	NE SW	Sec/Twp/Rge	Sec 23 T28	BS R15E
Wichita State Office Bldg PLUGGING SECTION	2522 (gps)	feet from sou	uth section li	ne
130 S. Market, Room 2078 Wichita, Kansas 67202	3283 (gps)	feet from eas	st section lin	е
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Miller, Steve	SMI-OW1	
Operator License # 101	County	Wilson		
Operator: State Of Kansas Fee Fund	Well Total Depth	1000 est		feet
Name & Steve Miller (Mattix) Lease Project	Production Pipe:	NA	Size Feet	NA
Address	Surface Casing:	NA	Size Feet	NA
AB oil well Gas Well XXXXXX SWD	Well/ Input Well		D&A	
Other well as hereinafter indicated:				
Plugging Contractor: K-W Oil Well Service, Inc			Lic.#	3097
Address: 19450 Ford Road, Chanute, Kansas 66720				
Company to plug at: Hour: Day:	14	Month:	2	2011
Plugging proposal received from: Robert Kepley				
Company Name: K-W Oil Well Service, Inc		_Phone:	620-433-21	78
Were: Wash well to TD and then pump full of ceme	nt from btm to top.			
Plugging Proposal Re	•	Alan M. Dun	TECHNICIAN	
Plugging attended by Agent: All	_ Part	XXXXXX	- None	
Operations Completed: Hour: Day:	<del></del>	_	2	2011
Actual Plugging Report: The contractor set 45				
location and the well drilled to 390' thru wood. The drill	nine was removed.	and a 1" cem	ent string wa	as then
washed to 390'. The well was pumped full of cement from		·		
237 sacks of portland cement were used to plug well. T	om btm to top thru t	his cement st	ring. A total	of
	om btm to top thru t	his cement st	ring. A total	of
location restored.	om btm to top thru t	his cement st	ring. A total	of e
location restored.	om btm to top thru t	his cement st	ring. A total	of RECEIVE
	om btm to top thru t	his cement st	ring. A total	of RECEIVE
location restored.	om btm to top thru the well was cut off	his cement st	ring. A total	of e
37,99514 -95.73  Remarks: Control # 20110057-001	om btm to top thru the well was cut off	his cement st	ring. A total	RECEIVE
Remarks: Control # 20110057-001 (If additional description is necessary, use	om btm to top thru the well was cut off	his cement st	ring. A total	RECEIVE