CONSERVATION		API NUMBER 15-101-20,919-6000
200 COLORADO		W SW NE , Sec. 13 , T 19 S, R 28 W/K
	D DERBY BUILDING NSAS 67202	feet from N/% section line
TECHNICIAN'S	• S PLUGGING REPORT	feet from %/E section line
Operator Lic	cense # 6390 9067	Lease Name Maughlin Well # 1
Operator:	McDonald-Wallace Petroleum	County Lane
Name &	Company, Inc. and DaMar Resour P. O. Box 70	ces, Inc.
Address	Hays, KS 67601	
		Conductor Pipe: Size feet
		Surface Casing: Size 8 5/8 feet 261
		out Well D&AX
	•	License Number 5104
Address	P. O. Box 1413, Great Bend, KS	67530
		7 Month: January Year:19 84
VERBAL PLUGO	GING ORDERS GIVEN TO Larry Bo	oren
(company nar	ne) Blue Goose	(phone) 316-792-5633
were: to f	ill hole with heavy mud and pump	cement through drill pipe.
lst plu	g at 2000' with 50 sx cement	
2nd plu	g at 1260' with 50 sx cement	
Plugging Ope	erations attended by Agent?: All_	(TECHNICIAN) PartNoneX
Operations (27 Month: January Year: 19 84
Operations (GING REPORT 1st plug at 2000' wi	th 50 sx cement, 2nd plug at 1260' with
Operations (ACTUAL PLUGO 50 sx co	GING REPORT 1st plug at 2000' wi ement, 3rd plug at 310' with 50	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge,
Operations (ACTUAL PLUGO 50 sx co	GING REPORT 1st plug at 2000' wi ement, 3rd plug at 310' with 50	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge,
Operations (ACTUAL PLUGO 50 sx co	ement, 3rd plug at 310' with 50 plug at 40' cement to surface	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge,
Operations (ACTUAL PLUGO 50 sx co	ement, 3rd plug at 310' with 50 plug at 40' cement to surface	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate
Operations (ACTUAL PLUGO 50 sx co	ement, 3rd plug at 310' with 50 plug at 40' cement to surface	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate
Operations (ACTUAL PLUGO 50 sx co	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement.	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, se with 10 sx cement. 6th plug to circulate
Operations (ACTUAL PLUG(50 sx control hulls - rathole	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement.	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing
Operations (ACTUAL PLUG(50 sx control hulls - rathole	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement.	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing
Operations (ACTUAL PLUG(50 sx condults - rathole Remarks:	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel,	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing STATE CORPORATION COMM
Operations (ACTUAL PLUG(50 sx control hulls - rathole Remarks:	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel,	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing STATE CONFORATION COMMINISTRATION COMMINISTRATION COMMINISTRATION COMMINISTRATION STATE ON SERVICE STATE CONFORATION COMMINISTRATION C
Operations (ACTUAL PLUG(50 sx control hulls - rathole Remarks:	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel,	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing STATE CORPORATION COMMINERS (INSTRUCTION DIVISION DI PROPRIMI DI
Operations (ACTUAL PLUG(50 sx control hulls - rathole Remarks: I herel and that I	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel,	th 50 sx cement, 2nd plug at 1260' with sx cement, 4th & 5th plugs solid bridge, e with 10 sx cement. 6th plug to circulate 3% cc. by Sun Cementing STATE CORPORATION COMM FEB 02 1984 g instructions were given as herein stated
Operations (ACTUAL PLUG(50 sx control hulls - rathole Remarks: I herel and that I	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel, by certify that the above plugging (**** / did not) observe this plugg	sx cement, 4th & 5th plugs solid bridge, with 10 sx cement. 6th plug to circulate state componenting STATE CORPORATION COMMILE FEB 02 1004 ging. Signed CHARICIAN)
Operations (ACTUAL PLUGO 50 sx co hulls - rathole Remarks: I herel and that I	ement, 3rd plug at 310' with 50 plug at 40' cement to surface with 15 sx cement. Use 60/40 Pozmix 2% gel, by certify that the above plugging (**** / did not) observe this plugg	sx cement, 4th & 5th plugs solid bridge, with 10 sx cement. 6th plug to circulate state componenting STATE COMPONENTION COMMIN FEB 02 1004 ging. Signed Caul A. Little: Signed Caul A. Little: