RANSAS

Form CP-3 Rev. 6-4-68

## STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

RECEIVED STATE CORPORATION COMMISSION

J. Lewis Ercch
Administrator
P. O. Box 17027
Wichita, Kansas 67217

MY. NO. 2508-W.

JAN 5 1973

COMSERVATION DIVISION Wichita, Kansas

C NW NE Sec. 26 Twp. 16 Rge. (E) (W)  County Ness Total Depth 4580°  Abandoned Oil Well Gas Well Input Well SWD Well D&A X  Other well as hereafter indicated  Plugging Contractor DNB Drlg.  Address Wichita, Kansas License No.  Operation Completed: Kour 9 A Day 1 Month 1 Year 1976  The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavywmid, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Complete Address	Suite 414, 200 E. Firat, Wichita, Kansas
Abandoned Oil Well Gas Well Input Well SWD Well D&A Z Other well as hereafter indicated  Plugging Contractor DNB Drlg.  Address Wichita, Kansas License No. Operation Completed: Four 9 A Day 1 Month 1 Year 1976 The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavywmud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Lease Name	Giess "B" Well No. 1
Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated  Plugging Contractor DNB Drlg.  Address Wichita, Kansas License No.  Operation Completed: Four 9 A Day 1 Month 1 Year 1976  The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavymud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Location	C NW NE Sec. 26 Twp. 16 Rge. (E) (W)
Other well as hereafter indicated  Plugging Contractor DNB Drlg.  Address Wichita, Kansas License No.  Operation Completed: Eour 9 A Day 1 Month 1 Year 1976  The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavywmid, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	County	Ness Total Depth 4580°
DNB Drlg.  Address Wichita, Kansas License No.  Operation Completed: Eour 9 A Day 1 Month 1 Year 1976  The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Abandoned Oil Well	Gas Well Input Well SWD Well D & A XX
Wichita, Kansas  Dicense No.  Operation Completed: Kour 9 A pay 1 Month 1 Year 1976  The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Other well as hereafter	indicated
Operation Completed: Four 9 A Day 1 Month 1 Year 1976 The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavywmud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Plugging Contractor	DNB Drlg.
Operation Completed: Four 9 A Day 1 Month 1 Year 1976 The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavywmud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.	Address	Wichita, Kansas License No.
The above well was plugged as follows:  RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.  I hereby certify that the above well was plugged as herein stated.	Operation Completed:	Hour 9 A Day 1 Month 1 Year 1976
RTD 4580° 8 5/8 csg set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel.  Gunned pits, circulated heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.  I hereby certify that the above well was plugged as herein stated.		
Gunned pits, circulated heavyward, set 70 sk cmt plug at 720° thru drill pipe.  Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.  I hereby certify that the above well was plugged as herein stated.		
Heavy mud to 240° set 20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid bridge & 10 sk cmt plug to base of cellar.  I hereby certify that the above well was plugged as herein stated.	RTD 4580 8 5/8 csg	set 317° cwc 180 sk. Plg. Mat. 50-50 poz 6% total gel
bridge & 10 sk cmt plug to base of cellar.  I hereby certify that the above well was plugged as herein stated.		
I hereby certify that the above well was plugged as herein stated.	Gunned pits, circulate	d heavsymud, set 70 sk cmt plug at 720° thru drill pipe.
	Gunned pits, circulate	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
	Gunned pits, circulate Heavy mud to 240° set	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
	Gunned pits, circulate Heavy mud to 240° set	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
	Gunned pits, circulate Heavy mud to 240° set	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
I hereby certify that the above well was plugged as herein stated.  VOICED Signed:	Gunned pits, circulate Heavy mud to 240° set	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
	Gunned pits, circulate Heavy mud to 240° set	d heavyymud, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid
	Gunned pits, circulate Heavy mud to 240° set bridge & 10 sk cmt plu	d heavyward, set 70 sk cmt plug at 720° thru drill pipe.  20 sk cmt plug thru drill pipe. Heavy mud to 40° set solid g to base of cellar.