KANSAS

Form CP-3 Rev. 6-4-68

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

J. Lewis Brock Administrator 245 North Water Wichita, KS 67202

INV. NO. 2968-W

MAR 2 9 1976

API Number 15 - 135 - 21,175

Co. (of this well)
Wichita, Kansas

Complete Address	304 Insurance Bldg	., Wichita, Kansas	
Lease Name	Pickering	Well No. 1	
Location	C S/2 SW SE		e(E)(W)_2
County	Ness	Total Depth	4538•
Abandoned Oil Well	Gas Well	Input WellSWD Well	D & A XX
Other well as hereaft	er indicated		
Plugging Contractor	Str		
Address	Wichita,	Ks. License No	o
Operation Completed:	11:30 P	ay 233 Month 3	Year 1976
The above well was pl	ugged as iollows:		
_	·	Plg. Mat. 50-50 poz 2%	total gel.
RTD 4538 8 5/8 csg	g set 261° cwc 180 sk	Plg. Mat. 50-50 poz 2% sk cmt plug at 720° thru	
RTD 4538 8 5/8 csg	g set 261° cwc 180 sk ted heavy mud, set 70		drill pipe.
RTD 4538 8 5/8 csg Gunned pits, circulat Heavy mud to 250 set	g set 261° cwc 180 sk ted heavy mud, set 70	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
RTD 4538 8 5/8 csg Gunned pits, circulat Heavy mud to 250 set	s set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
RTD 4538 8 5/8 csg Gunned pits, circulat Heavy mud to 250 set	s set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
RTD 4538 8 5/8 csg Gunned pits, circulat Heavy mud to 250 set	s set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
RTD 4538 8 5/8 csg Gunned pits, circulat Heavy mud to 250 set	s set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
Gunned pits, circulat Heavy mud to 250° set bridge & 10 sk cmt pi	g set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru lug to base of cellar	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40° set solid
Gunned pits, circulat Heavy mud to 250° set bridge & 10 sk cmt pi	g set 261° cwc 180 sk ted heavy mud, set 70 t 20 sk cmt plug thru lug to base of cellar	sk cmt plug at 720° thru drill pipe. Heavy mud to	drill pipe. 40' set solid