

1 090317

To: STATE CORPORATION COMMISSION  
CONSERVATION DIVISION - PLUGGING SECTION  
200 COLORADO DERBY BUILDING  
WICHITA, KANSAS 67202

API NUMBER 15- 101-21,143 -00-00

SW SE NW, SEC. 30, T 16 S, R 28 W/EX

2970 feet from N/S section line

3630 feet from W/E section line

TECHNICIAN'S PLUGGING REPORT

Operator License # 5405

Lease Name Tillotson "A" Well # 1

Operator: Oil Capital Corporation

County            Lane 15D.64

Name & Address 520 Farmers & Bankers Building

Well Total Depth 4635 feet

Wichita, KS 67202

Conductor Pipe: Size            feet

Surface Casing: Size 8 5/8 feet 387 ✓

Abandoned Oil Well            Gas Well            Input Well            SWD Well            D&A X

Other well as hereinafter indicated           

Plugging Contractor Abercrombie Drilling, Inc. License Number 5422

Address 801 Union Center, Wichita, KS 67202

Company to plug at: Hour: 10:30 pm Day: 29 Month: March Year: 19 85

Plugging proposal received from Wayne Shively

(company name) Abercrombie (phone) 316-262-1841

work: to fill hole with heavy mud and spot cement through drill pipe

1st plug at 2160' with 50 sx cement

2nd plug at 1710' with 50 sx cement

3rd plug at 450' with 50 sx cement  
solid bridge

4th plug hulls - plug at 40' -- cement to surface with 10 sx cement.

6th plug to circulate rat hole with 15 sx cement

Plugging Proposal Received by Robert B. Tarbutton  
(TECHNICIAN)

Plugging Operations attended by Agent?: All            Part            None X

Operations Completed: Hour: 2:30 am Day: 30 Month: March Year: 19 85

ACTUAL PLUGGING REPORT 1st plug at 2160' with 50 sx cement, 2nd plug at 1710' with 50

sx cement, 3rd plug at 450' with 50 sx cement, 4th & 5th plugs - solid bridge - hulls -

plug at 40' -- cement to surface with 10 sx cement, 6th plug to circulate rat hole with

15 sx cement.

RECEIVED  
STATE CORPORATION COMMISSION

APR 04 1985

Remarks: Used 60/40 Pozmix 2% gel 3% cc by Sun # 26520 CONSERVATION DIVISION  
(if additional description is necessary, use BACK of this form.)

Signed Robert B. Tarbutton  
(TECHNICIAN)

(XXX/ did not) observe this plugging.

4-9-85  
7537