		2-28	142
To:	1 C70646	•	1 //0674 0 0
	RPORATION COMMISSION	AP! NUMBER 15- 101-21	
200 COLOR	TION DIVISION - PLUGGING SECTION RADO DERBY BUILDING	SW SW NW, SEC.	, T16s, R29w, MEX
WICHITA,	KANSAS 67202	fee	t from S section line
TECHNICIA	AN'S PLUGGING REPORT		t from E section line
Operator	License # 5420 & 7245	Lease Name Jasper	Well # 1-6
	. White & Ellis Drilling, Inc. &	CountyLane	144.63
Name& Address	Texas-El Dorado Oil Company	Well Total Depth	
	401 East Douglas, Suite 500		feet_
	Wichita, KS 67202	Surface Casing: Size	
Abandoned	d Oli WellGas Well	_	
	it as hereinafter indicated		
Plugging	Contractor White & Ellis Drilling	. Inc. Lice	nse Number 5420
	401 East Douglas, Suite 500, Wich		
Company 1	to plug at: Hour: <u>10 p.m.</u> Day:_	27 Month: 2	Yang 10 89
	proposal received from Bob Kaspe		7847.19
(company	name) White & Ellis Drilling, In	C.	(phone) 316-263-1102
	n fill hole with heavy mud and spo		Elevation 2659
	at 2080' with 50 sx cement, 2nd		
	at 360' with 40 sx cement, 4th p		<del></del>
	to circulate rathole with 15 sx c		
Sell Prok	to circulate latitore with 15 3x c	emeric.	
	Plugging Room	T. T.	) C
	rlugging Prop	osal Received by I	(TECHNICIAN)
Plugging	Operations attended by Agent?: A	Part	None
	s Completed: Hour: 12 a.m. Day:_		· · · · · · · · · · · · · · · · · · ·
	UGGING REPORT 1st plug at 2080' w		
2nd_plug	at 1500' with 80 sx cement,		-OFINED
	at 360' with 40 sx cement,		RECEIVED COMMISSION
	at 40' with 10 sx cement,	STATE	DAFOIT 1 1003
	to circulate rathole with 15 sx c	ement.	·· ・ カダードハイ
· _ <u>ÿ</u> .		·	CONSERVATION DIVISION  CONSERVATION DIVISION
			CONSERVATION Kaness

Remarks: <u>Head 60/40 Pozmix 6% gel by Allied.</u>
(If additional description is necessary, use <u>BACK</u> of this form.)

DATE 3-6-89

MY. NO. 2406/2-28

Signed Dan Hoobson (TECHNICIAN)

CARD MUST BE TYPED	N	SIZIC OF TAITER	NTION TO DRILL	CARD MUST BE SIGNED
	11			
Expected Spud Date	10	(see rules on 88	reverse side) API Number 15 (0/ == 3	21,496-00-00
operator: Lirense #	5420 1 7	year 1245 & Texas-El	2970'	16S 29 X West Ft. from South Line of Section
Address 401. E Douglas City/State/Zip Wichita, KS	67202	500	4950'	
Contact Person Michael L Phone (316) 26	. Consid	ine	Nearest lease or unit bound	ary line 330° feet
CONTRACTOR: License #	5420	Tno	Lease NameJasp	er
Name White & Ellis D City/State Wichita, KS 6			Ground surface elevation Domestic well within 330 fe	
	ell Class:	Type Equipment:	Municipal well within one r	nile:yes Xno
<del></del>	_ Infield	X Mud Rotary	Depth to bottom of fresh wa	11001
	_ Pool Ext.	Air Rotary		vater 1100.
	Wildcat	Cable	Surface pipe by Alternate:	set 310 t
If OWWO: old well info as follows:			Surface pipe planned to be	Nône
Operator			Conductor pipe required	4450 '
Well Name Old To			Formation M1	ssissippion
I certify that well will comply with				
Date 11-22-88 Signature	e of Operator	XXXXX Mucha	il & Crawane Till	e. Sec/Treas
	e or Operator	_	l L. Considine	<del></del>
For KCC Use: Conductor Pipe Required	faat:			
Conductor Pipe Required	-2-89	minimum surface i ip	Approved By LKN/ 12-	2-88
This Authorization Expires			Approved by 19 8.7.19	
- FFFFGHVF DATE:	- 0 8	3/0 - 85	k" N	o, /
	. 60		w (we	9/
5/1/ 2-2	037		_	Face
			SW SW NW _ 6	Twp. 16S S, Rg. 29 X West
•				
·				wp
·			The state of the s	
·	PLUC	GGING PROPOSA	L IF ABOVE IS D & A	
mi i di si sana di Mbanaia			L IF ABOVE IS D & A	,
			L IF ABOVE IS D & A	rior to setting surface casing (call 7 a.m. to
This plugging proposal will be revie 5 p.m. workdays).			L IF ABOVE IS D & A	,
5 p.m. workdays).	wed and appr	roved or revised at the ti	L IF ABOVE IS D & A me the district office is called p	,
5 p.m. workdays).  1st plug @ ft. deep	wed and appr	roved or revised at the ti	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	wed and appr	roved or revised at the ti or formation with or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	0	roved or revised at the ti or formation with or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	0 0 0	roved or revised at the ti or formation with or formation with or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	0 0 0	or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	0 0 0	or formation with or formation with or formation with or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	0 0 0	or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep		or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep		or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep		or formation with	L 1F ABOVE IS D & A  me the district office is called p	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  1st plug @ ft. deep	wed and appr	or formation with	L IF ABOVE IS D & A  ine the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appr	or formation with	L 1F ABOVE IS D & A  me the district office is called p	sehole to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appr	or formation with	L IF ABOVE IS D & A  ine the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appr	or formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	rior to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appr	or formation with SX.	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appropriate to the second sec	or formation with SX.	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	wed and appropriate to the second sec	or formation with SX.	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to setting surface casing (call 7 a.m. to
5 p.m. workdays).  Ist plug @ ft. deep	A DATE LE	or formation with SX.	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	A DATE LE	or formation with SX.	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	A DATE LE	or formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	Marine & DATE Land of the Color	or formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	Marine & DATE Land of the Color	or formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	Marine & DATE Land of the Color	or formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	Marine & DATE Land of the Color	browed or revised at the tier formation with	L IF ABOVE IS D & A  me the district office is called p  50 sx. feet of. 60 sx. feet of. 40 sx. feet of. 10 sx. feet of. (b) Mou	sehole to sectors with contract to the contrac
5 p.m. workdays).  Ist plug @ ft. deep	Marine & DATE Land of the Color	or formation with	The CIRCULATED W/ SX feet of the district office is called possess for the district office is called possess feet of the same	sehole to sectors with contract to the contrac